SURVEY & REMONUMENTATION

JAN 18 2001

	SEC	TiOi
corners in		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

I. Public Land Survey T. IN. R. 2W T. R. Passis James T. R. Passis T. R. Passis T. R. Passi	For corners in		GA TOWNSHIP	1910	
1. Public Land Survey TRR TRR TRR TRR TRR TRR TRR TRR TRR T	INGHAM	Located In:	Corner Code #		
TR R Payls Johnson RECORD Controlling S TR R RECORD Set 10 0 2004-05382 2. Property Controlling S TR R RECORD Set 10 0 2004-05382 3. Miscellaneous S T R R Recorded Plat Set 10 0 2004-05382 3. Miscellaneous S T R R Recorded Plat Recorded	(County)				
2. Property Controlling S_T_R	1. Public Land Survey		К-3		
2. Property Controlling S_T_R	-	T R	INGHAM COUNTY REGISTER OF DEEDS		• • •
3. Miscellaneous S T R Property in Sec. S T R 4. Lot No. , Recorded Plat 5. Private Claims 1. BOM HISSE. , in a field survey on OCT.17. 20.00 do hardry state that under requirements of P.A. 74. Mediagn P.A. of 1970, the corner points mendioned in lines 1 and 2 above ware in conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with regulations and rules therefore as required in the conformance with the crises of the Mediagn Bourse of a Court of Lawy setablished, recreatabilished, monamented, recovered, found as expressed below. NOTE: Not more than 2 comers, all in the same town and range, risy be recorded on this conflictate. A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT, POST SET BY N. PARKE, U.S. DEPUTY SURVEYOR, OCT., 1225 A. CHAINS MORTH OF K-4, TAM. 10°, NGSW, 16 LINKS; B. ASH, 10°, NSIE; B. LINKS. 1) VOL. 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BLUT REPERS TO IT ON A MAR. 2) VOL. 2, P. 191, MAR. 16, 1864, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BLUT REPERS TO IT ON A MAR. 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 1898. (CONTINUED ON BACK SIDE) B. DEScription of corner evidence found and/or method applied in restoring or reestabilishing corner: FOUND THE 1/2° REROD INCASED IN A 4° CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5° ± WEST OF CENTERLINE OF EXAMENCE AND AND A CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5° ± WEST OF CENTERLINE OF EXAMENCE AND AND A CONCRETE COLLAR MONUMENT BOX 2.5° ±		STR		CRNR 11.	2000-045382
1. BON HEISE. I. BON HEISE. I. BON HEISE. I. In a field survey on _OCT. 17 _ 20.00 do hereby. I. BON HEISE. I. BON HEISE. I. In a field survey on _OCT. 17 _ 20.00 do hereby. Interest at that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of auryen interceins of the United States Department of the Interior, Paymen of Land Management of by a diaces of a Court of Law and for that the corner points mentioned in lines 3, 4 and 2 above were in conformance with the rules of the Michigan Bader of Land Surveysors of by a diaces of a Court of Law and for that the corner points mentioned in lines 3, 4 and 2 and 3 an		S T R S T R	-	Register of	
1. BON HEISE. I. BON HEISE. I. BON HEISE. I. In a field survey on _OCT. 17 _ 20.00 do hereby. I. BON HEISE. I. BON HEISE. I. In a field survey on _OCT. 17 _ 20.00 do hereby. Interest at that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of auryen interceins of the United States Department of the Interior, Paymen of Land Management of by a diaces of a Court of Law and for that the corner points mentioned in lines 3, 4 and 2 above were in conformance with the rules of the Michigan Bader of Land Surveysors of by a diaces of a Court of Law and for that the corner points mentioned in lines 3, 4 and 2 and 3 an	4. Lot No , Reco	orded Plat	*		
1, BON HEISE. 1, in a field survey on _OCT. 17 _ 20_00_ do hereby state that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Byrone of Land Management of by a dieces of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bade of Lend Survey or 5 by a dieces of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bade of Lend Surveyors or by a dieces of a Court of Law; setablished, re-established, menumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, misy be recorded on this coefficiate. A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT: POST SET BY H. PARKE, U.S. DEPUTY SURVEYOR, O.T., 1825 40 CHAINS NORTH OF K-4, TAMI, 10°, NGSW, 16 LINKS; B. ASH, 10°, N81E, 13 LINKS. 11 VOL. 1, P. 26, NOV. 27, 1944, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CONNER BUT REFERS TO IT ON A MAPP. 21 VOL. 2, P. 191, MAR, 16; 1854, CO. SURVEYOR, A. JACKSON COES OR TIDENTIFY OR MENTION THIS CONNER BUT REFERS TO IT ON A MAPP. 21 VOL. 2, P. 256, MAR, 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 102" REROD INCASED IN A 4" CONCRETE MONIMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLING OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLING OF ANNIS ROAD TO THE EAST. FOUND A DEAD 1** ELEM ENG AS A SOUTH SIDE FOUND THE INCORDAN IN A STOUTH OF THE POSITION OF THE 1/2" REROD AND 4" ELEMENT EXPONENTIO				A B C D	E F G H I J K L
state that under requirements of P.A. 74, Michigan P.A. of 1970, the somer points mensioned in lines 1 and 2 above were in conformance with requirement in the current mensioned in lines 1, and 2 above were in conformance with requirement of the Interior, Burnau of Land Management of by a decree of a Court of Law and for that the corner points mensioned in lines 3, 4 and 2 and	I, RON HELSEL	, in a field survey on OCT.		v .	1-3-1-1-
current manual of survey instructions of the United States Department of the Interior, Burseu of Land Management of by a decree of a Court of Law and of that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established,	state that under requirements of	P.A. 74, Michigan P.A. of 1970,	the corner points mentioned in	1 1	9-10-11-12
and 5 above were in conformance with the rules of the Michigan Board of Lead Surveyors or by a conformance with the rules of the Michigan Board of Lead Surveyors or by a conformance with the rules of the Michigan Board of Lead Surveyors or by a conformance with the rules of the Michigan Board of Lead Surveyors or by a conformance with the rules of the Michigan Board of Lead Surveyors or by a conformance with the rules of the Michigan Board of Lead Surveyors or by a conformance with the rules of the Michigan Board of Lead Surveyors of the Survey	current manual of survey instructi	ons of the United States Departme	nt of the Interior, Bureau of Land	_	
Decree of a Court of Low; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT; POST SET BY H. PARKE, U.S. DEPUTY SURVEYOR, OCT., 1825 10	Management or by a decree of a and 5 above were in conformance	Court of Law and /or that the corr e with the rules of the Michigan I	ier points mentioned in lines 3, 4 Board of Land Surveyors or by a		16-15-14-13
NOTE: Not more than 2 corners, all in the same town and range, mizy be recorded on this cardificate. A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT: POST SET BY H. PARKE, U.S. DEPUTY SURVEYOR, OCT., 1825 40 CHAINS NORTH OF K-4. TAM. 10", N65W, 16 LINKS, B. ASH, 10", N81E, 13 LINKS, 13 1) VOL. 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 2) VOL. 2, P. 191, MAR. 16, 1854, CO. SURVEYOR, A. JACKSON CITES ORIGINAL MONUMENT AND WITNESS. 3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELM RINE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A 800VE. THE CULVENT UNDER ANNIS ROAD AD ASED REPREACED, FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY, ACCEPTED THE POSITION OF THE ROWE CORNER IN A ABOVE. SET STANDARD INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 /AS DESCRIBED ABOVE. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 /AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP SOUTH BOD OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP SOUTH BOD OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET SET 1/2" X 13" IRON BAR & CAP NO. 18994 SETWENEL LEGS OF ARROWS SIGN, N. AZ. 233", 15.22 FEET SET 178 AND ARCHARD STANDARD SECRET STANDARD STANDARD SECRET SET SET TO L-3 SIGNED BY AND ARCHARD SECRET SET TO L-3 SIGN	Decree of a Court of Law; establi	shed, re-established, monumented	, recovered, found as expressed	1 1	
on this cerdificate. A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT: POST SET BY H. PARKE, U.S., DEPUT SURVEYOR, O.CT., 1825 40 CHAINS NORTH OF K-4. TAM. 10°, N65W, 16 LINKS; B. ASH, 10°, N81E, 13 LINKS. 1) VOL 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 2) VOL 2, P. 191, MAR. 16, 1854, CO. SURVEYOR, A. JACKSON CITES ORIGINAL MONUMENT AND WITNESS. 3) VOL 3, P. 236, MAR, 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENE AS HER ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMFER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: INGHAM COUNTY DISK STAMFED P.A. 345, P.S. 18394 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 293", 15.22 FEET SET 1/2" X 187 IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293", 15.22 FEET SET 1/2" N. 187 IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293", 15.22 FEET SET 1/2" N. 187 IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293", 15.22 FEET WELL SET TO A STAND	Delow.	•	1	8 19 20	21 22 23 24
A. Description of original monument and accessories and/or subsequent restoration: ORIGINAL MONUMENT: POST SET BY H. PARKE, U.S. DEPUTY SURVEYOR, OCT., 1825 40 CHAINS NORTH 10F K-4. TAM. 10°, N65W, 16 LINKS; B. ASH, 10°, N81E, 13 LINKS. 11 VOL. 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 21 VOL. 2, P. 191, MAR. 16, 1864, CO. SURVEYOR WA. ACKESON CITES ORIGINAL MONUMENT AND WITNESS. 31 VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR WA. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. DESCRIPTION OF CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5° ± WEST OF FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5° ± WEST OF CENTERLINE OF FDOAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANINS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANINS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A BOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT BOY. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT BOY. SET STANDARD INCHARD THE PROVE CORNER IN 3-45. 25 FEET SET 1/2" A 13" ROND BA		s, all in the same town and range,	may be recorded	9	
ORIGINAL MONUMENT: POST SET BY H. PARKE, U.S. DEPUTY SURVEYOR, OCT., 1825 40 CHAINS NORTH OF K-4, TAM. 10°, NOSW, 16, LINKS; B. ASH, 10°, NSIE, 13 LINKS. 1) VOL. 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 2) VOL. 2, P. 191, MAR. 16, 1854, CO. SURVEYOR, A. JACKSON CITES ORIGINAL MONUMENT AND WITNESS. 3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. DESCRIPTION OF CORNER CONTINUED ON BACK SIDE) B. DESCRIPTION OF CORNER CONTINUED ON BACK SIDE) CENTERLING OF EDGAR ROAD AND 2° ± SOUTH OF CENTERLING OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14° ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULIVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEARNING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2° REROD AND 4° DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET INGHAM COUNTY DISK STAMFED P.A. 345, P.S. 18394 AS DESCRIBED ABOVE. CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 293°, 15.22 FEET SET 1ALL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED DAST, 2633.85 FEET TO L.3 DATE OF THE POST OF THE POST OF THE POST ON T	on this certificate.			10-30-29-	28 27 26 25
ORIGINAL MONUMENT: POST SET BY H. PARKE, U.S. DEPUTY SURVEYOR, OCT., 1825 40 CHAINS NORTH OF K-4, TAM. 10°, NOSW, 16, LINKS; B. ASH, 10°, NSIE, 13 LINKS. 1) VOL. 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 2) VOL. 2, P. 191, MAR. 16, 1854, CO. SURVEYOR, A. JACKSON CITES ORIGINAL MONUMENT AND WITNESS. 3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. DESCRIPTION OF CORNER CONTINUED ON BACK SIDE) B. DESCRIPTION OF CORNER CONTINUED ON BACK SIDE) CENTERLING OF EDGAR ROAD AND 2° ± SOUTH OF CENTERLING OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14° ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULIVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEARNING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2° REROD AND 4° DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. C. DESCRIPTION OF MONUMENT AS SABSH AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET INGHAM COUNTY DISK STAMFED P.A. 345, P.S. 18394 AS DESCRIBED ABOVE. CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 293°, 15.22 FEET SET 1ALL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED DAST, 2633.85 FEET TO L.3 DATE OF THE POST OF THE POST OF THE POST ON T	A. Description of original mo	nument and accessories and/or	subsequent restoration:	11	
1) VOL. 1, P. 26, NOV. 27, 1844, CO. SURVEYOR, A. JACKSON DOES NOT IDENTIFY OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 2) VOL. 2, P. 191, MAR. 16, 1854, CO. SURVEYOR, A. JACKSON CITES ORIGINAL MONUMENT AND WITNESS. 3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. DESCRIPTION OF CONTROL OF CONTR	ORIGINAL MONUMENT: POST	r set by H. Parke, U.S. Depl	JTY SURVEYOR, OCT., 1825		33 34 35 36
OR MENTION THIS CORNER BUT REFERS TO IT ON A MAP. 2) VOL. 2, P. 191 MAR. 16, 1854, CO. SURVEYOR, A. JACKSON CITES ORIGINAL MONUMENT AND WITNESS. 3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEER REPLACED, FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION of monument for corner and accessories established to perpetuate locating the position of the corner: INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293", 15.22 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293", 15.22 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED BAST, 2633.85 FEET TO L-3 Date Signed by Date				• 13	
MONUMENT AND WITNESS. 3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED, FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETIER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAIL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED BAST, 2633.85 FEET TO K-2 MEASURED EAST, 2633.85 FEET TO K-2 MEASURED EAST, 2633.85 FEET TO L-3				•	
3) VOL. 3, P. 236, MAR., 1896, CO. SURVEYOR W.A. ROWE "SET IRON POST AND TILE, NO WITNESSES TAKEN" 4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANINS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT AS ASS. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132", 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 152", 48.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED EAST, 2633.85 FEET TO L-3 Signed by JAMANUM. Signed by JAMANUM. Date		, 1854, CO. SURVEYOR, A. JA	CKSON CITES ORIGINAL		
4) P.A. 74 CORNER, LIBER 4, PAGE 344, SEPT. 9, 1978, R. LESTER, P.S. NO. 18998. (CONTINUED ON BACK SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. DESCRIPTION OF MONUMENT BOX. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAIL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED BAST, 2633.85 FEET TO L-3 SIGNED BOX AND		R96 CO SURVEYOR W A ROY	A/E "SET IBON POST AND TH	IE NO WITNESSES	TAVENI
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELM ENA AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 52°, 48.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED BAST, 2633.85 FEET TO L-3 Signed by Signed by JAM	4) P.A. 74 CORNER, LIBER 4	, PAGE 344, SEPT. 9, 1978, F	R. LESTER, P.S. NO. 18998.	ce, No Wirkesse	·
FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELLE MENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 52°, 48.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAIL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED NORTH, 2652.07 FEET TO L-3 Signed by Signed by Signed Box		(CONTINUED ON	BACK SIDE)		•
FOUND THE 1/2" REROD INCASED IN A 4" CONCRETE MONUMENT IN A CONCRETE COLLAR MONUMENT BOX 2.5" ± WEST OF CENTERLINE OF EDGAR ROAD AND 2" ± SOUTH OF CENTERLINE OF ANNIS ROAD TO THE EAST. FOUND A DEAD 14" ELLE MENE AS THE ONLY REMAINING WITNESS BY LESTER IN 4-A ABOVE. THE CULVERT UNDER ANNIS ROAD HAS BEEN REPLACED. FOUND THE FENCE POSTS FROM 5-A ABOVE. BOTH WERE LEANING AND HALF ROTTED AWAY. ACCEPTED THE POSITION OF THE 1/2" REROD AND 4" DIAMETER CONCRETE MONUMENT AS FAITHFUL PERPETUATION OF THE ROWE CORNER IN 3-A ABOVE. SET STANDARD INGHAM COUNTY DISK ON THE 1/2" REROD AND 4" CONCRETE, WITH A STEEL MONUMENT BOX. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 52°, 48.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAIL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED NORTH, 2652.07 FEET TO L-3 Signed by Signed by Signed Box					
INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 52°, 48.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAIL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED EAST, 2633.85 FEET TO L-3 RON HELSEL LAND SURVEYOR No. 18994	FOUND THE 1/2" REROD I CENTERLINE OF EDGAR ROAI THE ONLY REMAINING WITNI FENCE POSTS FROM 5-A ABO AND 4" DIAMETER CONCRET	NCASED IN A 4" CONCRETE IN DE AND 2" ± SOUTH OF CENTE ESS BY LESTER IN 4-A ABOVE OVE. BOTH WERE LEANING AN E MONUMENT AS FAITHFUL!	MONUMENT IN A CONCRETE FRLINE OF ANNIS ROAD TO THE CULVERT UNDER ANNID HALF ROTTED AWAY, ACREPETUATION OF THE ROW	COLLAR MONUME THE EAST. FOUND IIS ROAD HAS BEE CCEPTED THE POSI /E CORNER IN 3-A	A DEAD 14" ELM ENE AS N REPLACED. FOUND THE TION OF THE 1/2" REROD ABOVE.
INGHAM COUNTY DISK STAMPED P.A. 345, P.S. 18994 AS DESCRIBED ABOVE. CUT "V" AT TOP SOUTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 132°, 45.32 FEET CUT "V" AT TOP NORTH END OF 24" C.M.P. UNDER ANNIS ROAD, N. AZ. 52°, 48.32 FEET SET 1/2" X 18" IRON BAR & CAP NO. 18994 BETWEEN LEGS OF ARROW SIGN, N. AZ. 293°, 15.22 FEET SET NAIL & TAG NO. 18994 SOUTH/SIDE POWER POLE, N. AZ. 309°, 62.85 FEET MEASURED NORTH, 2652.07 FEET TO K-2 MEASURED EAST, 2633.85 FEET TO L-3 RON HELSEL LAND SURVEYOR No. 18994					
RON HELSEL LAND SURVEYOR No. 18994 Date	INGHAM COUNTY DISK S'CUT "V" AT TOP SOUTH END CUT "V" AT TOP NORTH END SET 1/2" X 18" IRON BAR & SET NAIL & TAG NO. 18994 MEASURED NORTH, 2652.07	TAMPED P.A. 345, P.S. 18994 O OF 24" C.M.P. UNDER ANNIS O OF 24" C.M.P. UNDER ANNIS CAP NO. 18994 BETWEEN LEC SOUTH/SIDE POWER POLE, N. FEET TO K-2	l AS DESCRIBED ABOVE. 5 ROAD, N. AZ. 132°, 45.32 5 ROAD, N. AZ. 52°, 48.32 I 6S OF ARROW SIGN, N. AZ.	FEET	the corner:
Signed by Son Helsel Date			•		1
Signed by Son Helsel Date			:		HELSEL LAND *** SURVEYOR
0-/ 25 00			·	19	
0-/ 25 00		/ .			The state of the s
	Signed by Son/K	elsef		Date	WWW. IN HOUSE
	Surveyor's Michigan License N	o. <u>18994</u>		Oct.	25,00

4) CONTINUED

"EXCAVATED HOLE 7.5' X 7.5' TO AN AVERAGE DEPTH OF 2' AT THE INTERSECTION OF THE CENTER LINES OF EDGAR AND ANNIS ROADS. FOUND 1/2" X 8" T-BAR IN BETWEEN LOGS USED FOR CORDUROY ROAD, 2' BELOW SURFACE OF ROAD, FOUND BROKEN TILE AROUND AND OVER BAR. BAR FOUND $\pm 2'$ SOUTH OF CENTERLINE OF ANNIS ROAD EAST AND OLD FENCE LINE WEST, AND $\pm 2.5'$ WEST OF CENTERLINE OF EDGAR ROAD NORTH AND SOUTH. ACCEPTED BAR AS CORNER CALLED FOR BY W.A. ROWE, MARCH 1896."

"SET 4" X 36" CONCRETE MONUMENT WITH 1/2" X 38" REROD WITH CAP #18998, AND CONCRETE COLLAR WITH COVER, AT LOCATION OF T-BAR BOLT DESCRIBED ABOVE"

NAIL & TAG, #18998, SOUTH SIDE 10" ELM, ENE, 114.72' (FOUND 14" DEAD ELM)

NAIL & TAG, #18998, NORTH SIDE 12" FENCE POST, NW, 37.87' (GONE)

PUNCHED HOLE IN CENTERLINE OF TOP OF NORTH END OF CULVERT, ENE, 43.17" (C.M.P.REPLACED)

- 7 ik 🔾

PUNCHED HOLE IN CENTERLINE OF TOP OF SOUTH END OF CULVERT, ESE, 42.30'

5) P.A. 132 SURVEY, LIBER 5, PAGES 910-911, JAN. 30, 1989, B. ANTCLIFF, P.S. NO. 25826. "1/2" BAR IN CON. MON. IN MON. BOX" N&T 24" ELM 114.5' (DEAD) 80D AZ.,

N&T IN POST 317D AZ. 30.5

132d AZ., N& T IN FENCE POST 36.3' (FOUND LEANING AND IN POOR SHAPE)

N&T IN 10" ELM 95.4' (GONE) 23D AZ.,

6) P.A. 132 SURVEYS, R. HELSEL P.S. NO.18994, LIBER 6, PAGES 1155-1156, APRIL 12, 1993; LIBER 6, PAGES 1231-1232, JUNE 25, 1993; AND IN LIBER 7, PAGES 107-109, MAR. 4, 1994. ALL CALLED FOR THE SAME MONUMENT AND WITNESSES AS 5-A ABOVE.



SURVEY & REMONUMENTATION

JAN 1 8 2001

SECTION