LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Liber

B.A. 345 INGHAM COUNTY PEER APPROVED 11 14 96

9 Page

98

1. Public Land Survey T_2N_R_2W T_R T_R T_R 2. Property Controlling S_T_R in Section S_T_R 3. Miscellaneous S_T_R Property in Sec. S_T_R T_R T_R T_R T_R T_R T_R T_R	B-9	FILED 960045037 11/22/1996 13:34:49 REGISTER OF DEEDS Paula Johnson INSHAM COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		ABCDEFGHIJKL
I, Maurice H. Mahieu, in a field survey on October 29, 1996 do hereb P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 a with regulations and rules therefore as required in the current manual o States Department of the Interior, Bureau of Land Management or by a that the corner points mentioned in lines 3, 4 and 5 above were in c Michigan Board of Land Surveyors or by a Decree of a Court of monumented, recovered, found as expressed below:	y state that under requirements of and 2 above were in conformance if survey instructions of the United decree of a Court of Law and for onformance with the rules of the	2
NOTE: Not more than 2 corners, all in the same town and range,	may be recorded	8 .192021
on this certificate.		9 - 29 - 28 - 27 - 26 - 25
A. Description of original monument and accessories and/or st	ubsequent restoration:	
1. The Original GLO corner was set by H. Parke in Feb. 1826 40 chains West of the Northeast Corner of Section 19. Witnesses: Beech 22" N54E 40 links Beech 9" S61W 16 links 2. On February 10, 1852 A. Jackson, County Surveyor used the corner and states in		
Book 1, Page 271. Beech 22" N54°E 40 links Beech 9" S61°W 16 links 3. On July 6, 1869 County Surveyor T. J. Brown used corner. He crossed out the witnesses in GLO Book mentioned in A-1 and wrote in margin: Sugar 4 in S63 1/4°E 74 2/3 links Beech 10 in N59 1/2°W 76 1/3 links (T. J. Brown survey is recorded in book 2, Page 77)		
	See Part	A continued on back
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
Found 3/4" x 15" iron rod with pointed end in centerline To Centerline 18" Cherry S20°W 20.4' and small piece of ora diameter hole around 3/4" rod to depth of 4 feet. All sand 3/4" x 24" iron rod with cap stamped PA 345, PS 28414 in construction of new garage. The location of the 3/4" rod a is no other evidence to dispute this corner.	material except 4" of gravel location of found 3/4" rod. Tappears to be the best location	road. Excavation is in cut area of road. Se The fence line to north was obliterated by an of the perpetuation of the corner as there
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		
Set 3/4" x 24" iron rod with cap stamped "PA 345 PS #284 Nail and Tag #28414 South side Twin 15" Cherry N65°E 3 Nail and Tag #28414 East side 24" Maple S5°E 27.85 fee Nail and Tag #28414 West side 18" Cherry S20°W 20.68 Corner of House Foundation #6249 S30°E 78.42'	39.58 feet et	
Signed by Maurin Hollahi		11-15-96
		•
Surveyor's Michigan License No. 28414	all	•
MAURI	W.	AN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1 REVISED JAN., 1 REVISED OCT., 1

MAHIELI

Part A Continued

4. A LCRC in Liber 4, Page 186 was recorded by Laverne J. Hendryx P.S. 3276 on April 11, 1977. He states "Found 3/4" iron rod on Nort South fencelines", Witnesses:

Nail and Tag NE side 16" Cherry S5°W 20.27' Nail and Tag South side 14" Elm N60°W 51.42' Nail and Tag South side Twin 8" Cherry, N60°E 39.95'

- 5. An Act 132 survey in Liber 2, Page 1250 was recorded by Laverne Hendryx P.S. 3276 on April 11, 1977. Gives no mention of corner mater or witnesses.
- 6. On March 31, 1978 CETA Remonumentation found 3/4" Iron rod. Witnesses:

Found Nail and Tag NE side 16" Cherry, S5°W 20.27' Found Nail and Tag South side 14" Elm, N60°W 51.42' Found Nail and Tag South side Twin 8" Cherry, N60°E 39.95'

7. An Act 132 survey in Liber 7, Page 279 was recorded by Larry A. Bryan P.S. 25832 on July 30, 1986 states: "Found 1/2" bar centerline Toli Road, fence, North and South, Liber 4, Page 186. Found Nail and Tag northeast side 20" Cherry S5°W 20.18'. Set Nail and Tag South side 2 Elm, N60°W, 51.24'. Set Nail and Tag South side Twin 8" Cherry, N60°E 39.95' "; distance to B8 = 2642.29'; distance to B9 = 2745.50'.

#ECORPTO 960045037 11/22/1996 13:34:49 REGISTER OF DEEDS Daula Johnson INGHEM COLNIY, MI

[[Del

a hedi

3