		uirement of Act 74, Mich. P.A. 1		9 Page	72
For corners in AURELIUS TOWNSHIP, INGHAM COUNTY	Located In:	Corner Code #		FILED)
Public Land Survey	T <u>2N</u> R <u>2W</u> T R T R	B-10		960045024 1/22/1996 13:3 REGISTER OF DE Paula Johnse INGHAM COUNTY	EEDS on
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR		Register of I		& File Numbe
4. Lot No, Record	ded Plat		A B C D	E F G H	I J K L
I, Maurice H. Mahieu, in a field survey on October 25, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded			5 -18 -17 - 7	16 - 15	11 12 12 13 14 13 14 14 15 14 15 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16
on this certificate. A. Description of original mor	nument and accessories and	Vor subsequent restoration	9		26 - 25
1. Corner not set in origina 2. County Surveyor A. Jack corner material noted; witne 3. County Surveyor Thoma cost.; witnessed by Beech 7	al GLO survey. kson on February 22, 184 essed by Beech 10 in S25° as J. Brown on January 27 in N13°W 8 lks and Beec as J. Brown on July 5, 186	1 assumed to set corner. No °E 7 lks. Book 1 Page 46.	er to be a post; w	itnessed by	<u> </u>
3. Description of corner evide	ence found and/or method a	See Part A contin			
North and West. Found no a Don Fluke (A-6), 3 of 4 witin 64.2'±, face of 12" stump (A: 679°W 37.7'±. Also, found	evidence of South fence li lesses have small square sh) N10°W 6.9'±, to face 1/2" iron rod with cap "L. E	e intersection. Area has been clea ine. Corner falls on East edge of v blaze marks in bark of face of tree 15" Basswood (13" Oak) S45°W 4 Bryan #25832 S80°W 3.80' from 2' 2" x 2" angle iron. The location of	woods. Found all e. Measured to fa l5.9'±, to face 15" " x 2" angle iron.	4 witnesses ace of 15" Oa Basswood (Set 3/4" x 2	set by Kay ak, N81°W (12" Oak) 4" iron rod

rock formation w/broken fence post as noted by L. Bryan appears to be the tie back post for the anchor corner post. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

perpetuated location of the corner set by T. J. Brown. The angle iron appears to be the perpetuation of the anchor post. Also the

Set 3/4" x 24" iron rod with cap stamped "PA 345 PS #28414" inside 2" x 2" angle iron.

Witnessed by:

Signed by _____

Nail and Tag #28414 East side 38" Oak, N10°W 37.21'

Nail and Tag #28414 East side 38 Oat, N10 W 37.21 Nail and Tag #28414 SW side 18" Basswood, N25°W 16.05' Nail and Tag #28414 East side 10" Maple, N45°W 55.35' Nail and Tag #28414 North side 18" Maple, West 34.77'

1/2" iron rod with cap "LxBryan #25832, S80°W 3.80"

11-15-96

Surveyor's Michigan License No. 28414



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,19
REVISED JAN, 19
REVISED OCT., 19

P.A. 345 INGHAM COUNTY

Part A Continued

5. LCRC recorded by Richard W. Steadman PS #11370 in Liber 5 Page 19 on October 9, 1978 states "Found anchor post at the intersection fences running North, South, East, and West.

Witnesses: 10" Ash N5°W 6.9 feet

30' Oak \$85°W 24.8 feet 5' Maple S10°W 15.7 feet

6. LCRC recorded by Kay Don fluke PS #18988 in Liber 6, Page 294 on June 17, 1985 states "Anchor post was destroyed by Bulldozing re corner from witnesses that were still in. Set 2" x 2" angle iron and put old fence post and stones by it and around it."

Witnesses: N5°W 6.90 feet Ash 10" S79°W 37.80 Oak 12"

S45°W 46.10 Oak 13" N81°W 54.30 Oak 10"

7. Unrecorded survey by Larry Bryan PS #25832 dated January 5, 1993 calls for "Found rock formation with broken of fence post 2' deep, Nail and Tag East side 20" Ash N05°W 15.7

bar and cap.

Nail and Tag North side 16" Maple, West 31.32' Nail and tag East side 16' Ash, S10°W 60.72' Distance to A-10 = 2748.48 feet

NI/SZ/1996 13:34:29 REGISTER OF DEEDS Paula Johnson INGHOM EDGNIY,MI

FIREL

15