

DEC 1 6 1996

COMMISSION

Surveyor's Michigan License No. 11370

	COMM					
			RNER RECORDATION CER juirement of Act 74, Mich.		ber 9	Page 105
For	corners in]	g= 1 1	ED
	GHAM COUNTY urelius Township	Located In:	Corner Code #		96004 12/02/1996	LED 5753
1. P	ublic Land Survey	T <u>2N</u> R <u>2W</u> TR TR TR			REGISTER Paula	OF DEEDS Johnson COUNTY, MI
ir 3. N	roperty Controlling Section liscellaneous roperty in Sec.	S T R S T R S T R		Regist	er of Deeds St	amp & File Numbe
4. L 5. P	ot No, Recon	ded Plat		1 A B C	D E F G	H I J K L
			•	3		
requi confo the U and A Mich	rements of P.A. 74, Michigan ormance with regulations and inited States Department of to or that the corner points mer	n P.A. of 1970, the corner points if rules therefore as required in the the Interior, Bureau of Land Man- ntioned in lines 3, 4 and 5 above yors or by a Decree of a Co	er 4, 1996, do hereby state that mentioned in lines 1 and 2 above the current manual of survey instructing agement or by a decree of a Court were in conformance with the rule runt of Law; established, re-established.	were in stions of tof Law 6 18 blished, 8 19	1716	-10 -11 -12 -13 -13 -22 -23 -24
NOT	E: Not more than 2 come on this certificate.	ers, all in the same town and i	range, may be recorded	10 30	29 28	272625
A.	Description of original mo	nument and accessories an	d/or subsequent restoration:	11 12 31	3233	343536
٠.	Parke "set		es, Deputy Surveyor Har ' Beech S70-1/2°W 23 lir .ks."			
		ord of Surveys, Vol. 1, F J. S. witnesses.	Page 42, County Surveyo	or Anson Jackson	used this co	rner and notes
		ord of Surveys, Vol. 1, F n notes the U. S. witnes	Page 99, County Surveyosses.	or Anson Jackson	again used t	his corner and
	(Continued on back)					
B.	Description of corner evi	dence found and/or method	applied in restoring or reestab	olishing corner:		
	iron pipe with concre directly under the pip	ete poured around it directe. Replaced the 1/2" in	site fence and tree line E ectly under the rod. Brok on rod with standard Ing 6.24 feet to G-1, 2643.42	e out the concrete ham County Remo	and found ponumentation	olow point n rod and
C.	Description of monument	for corner and accessories	established to perpetuate loca	ating the position of th	e corner:	
	Set 3/4" smooth iron 3/4" iron pipe and plo	rod and cap stamped "l ow point, and took the f	P. A. 345 PS 11370" in n ollowing witnesses (bear	nonument box ove ings are magnetic	er):	OF MICE. WILL
	(To C/L of tree = 4 Found nail and tag 1 Found nail and tag 1		nut S84°E 43.66 feet	/ 40.94 feet		ICHARD W. STEADMAN LAND SURVEYOR NO. 11370
Sig	ned by Rick	lad W. Ster	- Iman	es supremental establishment	William Control	AND SURVEY

Date November 2, 1996

G-2, T2N, R2W

Part A - Continued

- 4). 01-13-1866: Record of Surveys, Vol. 3, Page 21, Deputy County Surveyor T. J. Brown used this corner but gives no information about it other than referring to it as the quarter post on the west section line.
- 5). 01-01-1969: County Road Commission Comer Grid Sheet calls for a plow point witnessed by anchor post East 27.5 feet, 12" Walnut NW 42.3 feet, 12" Maple SW 51.2 feet.
- 6). 02-13-1973: Land Corner Recordation Certificate (Rec. 2-15-73, L2-P349), L. J. Hendryx, L.P.S. 3276 states "found RR Spike in center of blacktop road but it didn't check with old witnesses of 1945 that showed a plow point; walnut NW 42.3 feet, 12" Maple SW 51.2 feet."
- 7). March 1980: Certified Survey Map (Rec. 3-24-80, L3-P1229), A. C. Williams, L.P.S. 21275 calls for the "East 1/4 Cor. Sec. 4, T2N, R2W, nail in Walnut NW 42.3 feet, nail in 12" Maple SW 51.2 feet." He also gives a distance of 2645.24 feet to G-3.
- 8). March 1980: Certified Survey Map (Rec. 3-24-80, L3-P1233), A. C. Williams gives the same notation, witnesses, and distance as Item 7 above.

Time:

A pile - Ferm