NOV 1 5 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE - Filing Regulrement of Act 74, Mich. P.A. 1970

Jul 6 8 16 AH '94

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970					RESISTER OF DEEDS									
LNGHAM (County)	 ,	Located In:	Corner Code =11		,	(J.)	(A) (ري. الله:	нèя. ТҮ.	aas HIC	 :11.				
ALATEDON 1. Public Land Survey		T_3N_R_1W_ TR tR	I -10			i ui vi	ijers s								
2. Property Controlling		_ T R													
In Section 3. Miscellaneous		_ Ť· Ř		1											
Property in Sec.		_ T R _ T R		Itegisti	er of	Dee	ds St	amp	& F	ile	Nur	nbe	r		
4. Lot No, I 5. Private Claims	Recorded P	Plat		2	<u>А</u> В	C_	D E	F - 4	3	11	 -	ĸ	L	- -	
. bitth n tour		7711197	4 44					_ _		0	1	,	-1	2-	
I. DAVID R. LOHR do hereby certify that under red in lines 1 and 2 above were li current manual of survey instre	quirements on conformanuctions of the	of P.A. 74, Michigan P.A. ice with regulations are ie United States Depar	of 1970, the corner poblismen of rules therefore as required tment of the Interior, Bureau o	tloned 6 In the f Land 7	18		7	-16-		5—	_1	4-	_ 	3-	
Management or by a decree of above were in conformance will Court of Law, established, r expressed below:	a Court of La th the rules c	w and/or that the come of the Michigan Board o	er points mentioned in lines 3, 4 of Land Surveyors or by a Decr	tand5 a	- -	-}-	9	\dashv	-				_į	_	
NOTE: Not more than 4 c	orners, all	In the same town a	nd range, may be recorded		30									- -	

A. Description of original monument and accessories and/or subsequent restoration:

1 - 10

on this certificate.

1. POST SET BY MUSGROVE EVANS IN DECEMBER 1826, WITNESSED BY: ELN 10" SOUTH 55 DEG. EAST, 38 LINKS (23.76') B. ASH 6" NORTH 87 DEG. WEST, 17 LINKS (11.22')

2. NO OTHER REFERENCES FOUND IN COUNTY SURVEYORS RECORDS

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-10:

VISITED LOCATION OF CORNER AND FOUND 1/2" IRON/CAP #28414 AS PER LCRC L.7, PG. 154. FOUND ALL FOUR WITNESS TREES. ALSO FOUND SELLEK'S IRON 27.10 FT. SOUTH, HOWEVER I BELIEVE THAT THIS IRON HAD BEEN MOVED FROM ITS ORIGINAL LOCATION IN ROTTED FENCE POST. IRON WAS PROTRUDING 15" ABOVE GROUND AND DID NOT FIT SELLEK WITNESSES. TWO OF SELLEK'S WITNESS TREES ARE SAME AS MAHLEU USED (48" MAPLE WEST AND 20" MAPLE N 85 DEG.E) I ACCEPTED LOCATION OF MAHLEU'S 1/2" IRON IN REMAINS OF ROTTED ANCHOR POST AS THE TRUE CORNER, AND PUBLED SELLEK'S IRON. SET 3/4" X 24" STANDARD REMO

BAR AND P.A. 345 CAP #30090 IN 1" x 5' LONG PIPE SET IN 5 GAL PLASTIC BUCKF OF CHIPPED LIME STONE AND CONCRETE IN LOCATION OF MAHLEU'S IRON.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-10:

3/4" x 24" STANDARD REMON. BAR /PA 345 CAP #30090 IN 1"x5'PIPE SET IN 5 GAL. BUCKET OF LIME STONE AND CONCRETE. WITNESSED BY:

S/S 36" NAPLE, SW/S 24" MAPLE, FD. N&T #28414 85 DEG. AZ. 26.46' FD. N&T #28414 AZ, 135 DEG. 45.601 NW/S 32" MAPLE, SET N&T #30090 AZ. 200 DEG. 66.20 N/S 36" MAPLE, FD: N&T #28414 AZ. 270 DEG. 31.121 BEARING AND DISTANCE TO 1-9 AZ. 00-14-40 DEG. 2645.531 BEARING AND DISTANCE TO J-10 AZ. 89-51-25 DEG. 2604.671 BEARING AND DISTANCE TO II-10 AZ.270-38-17 DEG. 2717.231

Signed by David UI John Date
Surveyor's Michigan License No. 30090

Dale JUNE 28, 1994

DAVID R.
LOHR
PROFESSIONAL
SURVEYOR
NO.30090

OFESSIONAL
PROFESSIONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, REVISEO MAY 14, REVISEO MAY 14,

P.A. 345 INGHAM COUNTY
PEER APPROVED _6/8/74_17L

I-10 CONTINUED:

3. RECORDED SURVEY BY JOHN SELLEK, PS #2585, DATED 4/18/80, L4, PG.240-243. STATES: "SET 1/2" IRON AND CAP." WITNESSED BY:

P-K MULTI 48" ELM WEST 30.88' P-K 20" MAPLE N85E 26.88'

P-K 14" MAPLE N35E 38.25'

- 4. L.C.R.C. BY JOHN SELLEK, DATED 2/19/81, LIBER 6, PAGE 153. "SET 1/2" IRON AND CAP IN BASE OF FENCE CORNER POST." WITNESSES SAME AS ABOVE IN ITEM #3.
- 5. RECORDED SURVEY BY MAURICE MAHIEU, PS #28414, DATED 6/20/89, L.5, PG.1134. NO MENTION OF MONUMENT. WITNESSED BY:

 NAIL AND TAG NORTH FACE 24" NAPLE, S 45 DEG. EAST, 46.42'

 NAIL AND TAG SOUTH FACE 26" NAPLE, N 85 DEG. EAST, 26.46'

 NAIL AND TAG NORTH FACE 48" MAPLE, WEST, 31.21'

 NAIL AND TAG WEST FACE 32" MAPLE, S 20 DEG. WEST, 66.13'
- 6. L.C.R.C. BY MAURICE MAHIEU DATED 9/15/89, LIBER 7, PAGE 154.
 "FOUND OLD ROTTED FENCE POST AT INTERSECTION OF FENCES. SET 1/2" ROD WITH CAP IN LOCATION OF FENCE POST." WITNESSES SAME AS IN ITEM #4.

ķ

7. NO OTHER REFERENCES FOUND,