## DEC 1 6 1998

COMMISSION	LAND CORNER RECORDATION CERTIFIC	CATE Liber	<b>9</b> Page 63	3
For corners in	Filing Requirement of Act 74, Mich. P.A.	1970 	u EN	
INGHAM COUNTY Delhi Township	Located In: Corner Code #	11/14/	60043562 1996 10:59:18	
1. Public Land Survey	T <u>3W</u> R <u>2W                                   </u>	REGIS Pau	TER OF DEEDS la Johnson IAM COUNTY, MI	
2. Property Controlling S	T R	Register of Deeds	s Stamp & File Numb	be
4. Lot No, Recorded Plat, S. Private Claims		ABCDEF	G H I J K	L
		2 - 6 - 5 - 4	3 - 2	1-
with regulations and rules therefore as required States Department of the Interior, Bureau of that the corner points mentioned in lines 3.	n August 22, 1996, do hereby state that under requirements points mentioned in lines 1 and 2 above were in conformance red in the current manual of survey instructions of the United Land Management or by a decree of a Court of Law and /or 4 and 5 above were in conformance with the rules of the a Decree of a Court of Law; established, re-established, below:	3 4 - 7 - 8 - 9 5 6 - 18 - 17 - 16 7 8 - 19 - 20 - 21	13 11 1	12-
NOTE: Not more than 2 comers, all in the on this certificate.	e same town and range, may be recorded	9 10 30 29 28	27 26 2	5-
A. Description of original monument an	d accessories and/or subsequent restoration:	11 12 31 32 33	35-3	6-
1). 12-28-1826: U. S. Public Land	d Survey Field Notes, Deputy Surveyor Musgrove the 1/4 Sec. Cor. on an Elm 22" dia."	13	<u>T          </u>	Ĺ
2). 12-08-1840: Record of Surve Tree, 22" Elm."	ys, Vol. 1, Page 67, County Surveyor Anson Jacks	son notes "Corner		
3). 12-16-1871: Record of Survey almost gone."	ys, Vol. 3, Page 59, Deputy County Surveyor T. J.	Brown notes "Elm 22"	dia. corner tree nov	N
4). 01-01-1969: Ingham County F anch, post East 3	Road Commission Corner Grid Sheet calls for "sto	ne on P. (?), anch. posi	West 30.7 feet,	
(Continued on back)				
3. Description of corner evidence found	and/or method applied in restoring or reestablishing o	orner:		
Found axle shaft over stone in me standard Ingham County Remont	onument box in Eifert Road opposite fence line Eaumentation rod and cap.	ast and tree line West.	Replaced axle with	Í
C. Description of monument for corner ar	nd accessories established to perpetuate locating the p	position of the corner:		
Set 3/4" smooth iron rod and cap s and took the following witnesses (b	tamped "P. A. 345 PS 11370" in monument box pearings are magnetic):		E OF MICHIGAN	h.
Found nail and tag 11370 in S. side Set nail and tag 11370 in S. side 14 NE Corner of House Foundation S Found nail and tag 11370 in S. side Found 1/2" iron rod and cap 30090	4" Box Elder S74°E 38.62 feet 76°W 94.55 feet 9 Power Pole S87°W 43.58 feet	S LICETS	RICHARD W. STEADMAN LAND SURYEYOR NO. 11370	
D.D 11.1	C-1-1	1166	VAND SUR	•
igned by Kukaud W.	Steadman Date_	October 26, 1996	Mensenne	_
surveyor's Michigan License No	11370			

## G-12, T3N, R2W

## Part A - Continued

- 5). 4-02-1973: Land Corner Recordation Certificate (Rec. 4-05-73, L2-P411), R. M. Lester, L.P.S. 18998 "found 3/8" X 5/8" rectangular bar in centerline Eifert Road on fencelines East and West; nail and tag in N. side 12" twin maple West 61. 46 feet, nail and tag in E. side 30" Maple North 130.70 feet, nail and tag in W. side 10" Pine SE 55.09 feet."
- 6). 4-04-1973: Certified Survey Map (Rec. 5-11-73, L1-P718), R. M. Lester found a 3/8" bar and repeats the witnesses given in Item 5 above. He also gives a distance of 2650.96 feet to H-12.
- 7). 9-06-1973: Land Corner Recordation Certificate (Rec. 1-08-79, L5-P129), R. W. Steadman, L.P.S. 11370 found the iron bar called for In Item 5 above, and dug hole. Below was an iron axle shaft over a large pointed stone with small stones, broken tile and crockery around. Raised axle shaft to surface to replace iron bar, and set monument box; utility pole NE 80.79 feet; utility pole WSW 43.65 feet, NW corner of house SE 85.45 feet.
- 8). 9-06-1973: Certified Survey Map (Rec. 3-07-79, L1-P1141), R. W. Steadman "found 3/8" bar over axel, removed bar, raised axel, set mon. box; power pole NE 80.79 feet, power pole WSW 43.65 feet, NW cor. house SE 85.45 feet.
- 9). 12-04-1974: Certified Survey Map (Rec. 2-18-75, L2-P299), R. M. Lester calls for the W. 1/4 Cor. Sec. 34, T3N, R2W and gives the same witnesses as Item 5 above. He also give distances of 2639.67 feet to G-13 and 2650.96 feet to H-12.
- 10). 2-02-1978: Certified Survey Map (Rec. 3-10-78, L3-P252), A. C. Williams, L.P.S. 21275 notes "W. 1/4 Cor. Sec. 34, T3N, R2W, Liber 2-Pg. 411."
- 11). June 1978: Certified Survey Map (Rec. 7-19-78, L3-P441), R. M. Lester notes "W. 1/4 Cor. Sec. 34, T3N, R2W, Fd. 3/4" bolt" and lists the same witnesses as given in Item 5 above. He also gives the same distances as in Item 9 above.
- 12). 2-01-1988: Certified Survey Map (Rec. 7-02-90, L6-P233), L. A. Bryan, L.P.S. 25832 found a 1" bar in C/L Eifert Road on East-West fence; found N & T in N. side 20" Twin Maple West 61.33 feet, found N & T in S. side Power Pole S85°W 43.56 feet, found N & T in W. side 18" Pine S45°W 55.05 feet, found N & T in SE side Power Pole N45°E 80.86 feet, found bar and cap West 32.00 feet. He also gives distances of 2650.72 feet to H-12 and 2639.98 feet to G-13.
- 13). 10-26-1990: Certified Survey Map (Rec. 12-26-90, L6-P611), D. R. Lohr, L.P.S. 30090 notes "E. 1/4 Cor. Sec. 33, T3N, R2W, L5-P129; found iron in mon. box as witnessed" and lists the witnesses given in Item 7 above. He also gives a distance of 2640.14 feet to G-13.
- 14). 4-10-1992: Certified Survey Map (Rec. 4-12-93, L6-P1134), Ron Helsel, L.P.S. 18994 notes "E. 1/4 Cor. Section 33, T3N, R2W, L5-P129."

to to