3

DEC 0 5 1999

SECTION

Paula Johnson
INGHAM COUNTY
REGISTER OF DEEDS RECORDED
ENGER SURVEYING & ENGINEERI

L-9 P-485

1999-050547

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			1	
INGHAM COUNTY (County) LEROY TOWNSHIP	Located In:	Comer Code #		1999-050547
Public Land Survey	T <u>3N_R2E</u> TR TR TR	<u>L-11</u>		
2. Property Controlling S in Section S	TR			
3. Miscellaneous Property in Sec. S	TR TR		***************************************	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims				A B C D E F G H I J K L M
				2 6 5 4 3 2 1 1
I, <u>DAVID L. CLIFFORD</u> , state that under requirements of P.A. 74, Mich above were in conformance with regulations instructions of the United States Department of Court of Law and for that the corner points me rules of the Michigan Board of Land Surveyors monumented, recovered, found as expressed	nigan P.A. of 1970, the and rules therefore as of the Interior, Bureau intioned in lines 3, 4 ar s or by a Decree of a C	corner points mention required in the current of Land Management and 5 above were in co	ned in lines 1 and 2 nt manual of survey or by a decree of a nformance with the	4 7 8 9 10 11 12 15 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in the on this certificate.	same town and ran	nge, may be recorded	i	9 10 -30 -29 -28 -27 -26 -25 11 12 -31 -32 -33 -34 -35 -36
A. Description of original monument a	nd accessories and	t/or subsequent res	storation:	13
1. ORIGINAL POST SET BY J. WAMPL S221/2W 109	ER DS IN DEC. 18	825; ELM 12 S52E	7; WO 45	
2. TJ BROWN, COUNTY SURVEYOR, SURVEYOR RECORDS IN JAN. 1860 V LKS; W. OAK 16" S41½W 4 LKS;				ME 2 PAGE 368, INGHAM COUNTY OWING WITNESSES; W. OAK 20" N47½°W 44
3. WA ROWE, COUNTY SURVEYOR, RECORDS IN AUG. 1895 AS A BUGGY				ME 3 PAGE 240, INGHAM COUNTY SURVEYOR 1½W 243 LKS;
4. C. GARLOCK RLS # 14762 RECORDED IN LIBER 3 OF SURVEYS S75°W, 97.05' SPK. CL 42" W. OAK; N	PAGE 209 IN JUN	NE 1977 AS A FOU	ND 1/2" IRON RC	MAY 1978 AND USED IT IN A SURVEY DD; N65WE, 59.60' SPK. CL TELE. POLE; EET SIGN; S45°E, 84.35', CL UTIL. POLE.
	'; NAIL & TAG NOF	RTH SIDE 42" W. C		:. 1983 AS A FOUND 1/2" IRON ROD; NAIL IN FT.; NAIL & TAG TOP OF WOOD POST, 023°
B. Description of corner evidence found	i and/or method ap	plied in restoring o	r reestablishing co	orner:
4' EAST OF CENTERLINE HOUSE RO. 2' DEEP HOLE AROUND BAR AND FO	AD TO NORTH MA PUND BUGGY AXLI KAND HUGHES AN	ATCHING GARLOC E BENEATH BAR, ND CAPPED BAR	CK'S AND HUGHE ACCEPTED BUG WITH ALUMINUM	I PA 345 CAP AND SET MONUMENT BOX.
C. Description of monument for comer a L-11 T3N-R2E 5/8" X 24" STEEL BAR AND 21/4" ALUM FOUND NAIL & TAG #19834 IN NORTH FOUND NAIL & TAG #39100 (TERRY V	IINUM CAP STAMP I SIDE 42" OAK, S	PED PA 345 25	837 INGHAM CO	UNTY IN MONUMENT BOX
SET NAIL & TAG #25837, EAST SIDE FOUND NAIL & TAG #19834, TOP WO FOUND NAIL, SW SIDE UTIL. POLE, S	19" WALNUT, N10° OD POST, N28°E,	°W, 152.75′		DAVID L. CLIFFORD

P.A. 345 INGHAM COUNTY
PEER APPROVED 6/15/99 MC

Surveyor's Michigan License No. 25837

EVISED OCT., 199

SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSION