

SEP 01 1999

950003949 Liber8

Page569

27

50	S.do	P9"	ř	6	A
Ce		\mathbb{C}	1	U	1

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		1
	CITY OF EAST LANSING - MERIDIAN TWP.	FILED
INGHAM COUNTY	Located In: Corner Code #) ' (
		11/28/1995 14:13:51 REGISTER OF DEEDS PAULA JOHNSON
1. Public Land Survey	T <u>4N</u> R <u>1W B-4</u>	INGHAM COUNTY, MI
	<u>T </u>	
	TR]
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	Register of Deeds Stamp & File Number
Property In Sec.	S TR	1
4. Lot No, Reco	rded Plat	
5. Private Claims	add Fidi	A B C D E F G H I J K L

I, Maurice H. Mahieu, in a field survey on Oct. 23, 1995 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more that 4 comers, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1. This corner was not set in the original government survey.
- 2. Anson Jackson, County Surveyor, recorded corner in Liber 1, Page 233, County Surveyors Records on May 12, 1848. No material noted but witnessed with: W. Oak 23 N38 1/2E 21 1/2; R. Oak 24 S55 3/4E 39 1/2.
- 3. Anson Jackson, County Surveyor, recorded corner in Liber 3, Page 114, County Surveyors Records on July 28, 1856. No material noted but witnessed with: Sugar 11 N10 2/5W 21 1/2; W. Oak 23 N58 1/2E 21 1/2; Beech 24 S58E 21 3/4.
- 4. Anson Jackson, County Surveyor, recorded corner in Liber 3, Page 117, County Surveyors Records on July 3, Page 117. No material noted but witnessed with: W. Oak 23 N58 1/2E 21 1/2; Beech 24 S75W 17

See Part A continued on back.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

Found 4" concrete monument 0.45' south of East-West occupation fence line and at the south end of a occupation fence line to the north. This monument is refered to as the Southeast corner of Lot 207 and the Southwest corner of Lot 208 in the plat of Whitehills Estates No. 6 and as the interior corner of Section 7 and as the Northwest corner of Beechtree Sub. This surveyor accepts the monument as the corner based on the best location from the surrounding occupation line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 4" Concrete monument in postion and witnessed by: Face of 4" Steel fence post S05°E 8.62 feet Set nail and tag # 28414 east side of 12" Oak S08"W 18.24 feet Set nail and tag # 28414 east side of 10" Apple S28"W 6.68 feet Set nail and tag # 28414 east side of 8" Ash S82"W 4.92 feet

Surveyor's Michigan License No. 28414

P.A. 345 INGHAM COUNTY PEER APPROVED 11/21/95 R

P.A. 345 INGHAM COUNTY - APPROVED 11/21/95 4. . . . 1

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

MAHIPU SURVEYOR

NO.

REVISED JAN., 198:

Part A Continued

5. This corner was referred to in the following subdivisions: Whitehills Estates No. 5, Liber 18, Page 12; Whitehills Estates No. 6. Liber 21, Page 2; Whitehills Estates No. 7, Liber 23, Page 3; Whitehills Estates No. 8, Liber 24, Page 4; Beechtree Sub. Liber 33, Page 26; Rudgate Hills Liber 25, Page 5



SURVEY & REMONUMENTATION

SEP 01 1999

SECTION

A Part Control of the Control of the

....