

DEC 1.7 1995

I ACTION TO THE PROPERTY OF TH

## LAND CORNER RECORDATION CERTIFICATE

A A ማ

COMMISSION		Filing Requirement of Act 74, Mich. P.A. 1970 PER VVJ PAGE 410											
For corners in  IONIA (County)		Located In:		Corner Code #			STATE OF MICHIGAN IONIA COUNTY RECEIVED FOR RECORD						
1. Public Land Survey	, ·	T 5N R 5W T R T R		F-3			,			IR RECU 1=19 P.			
2. Property Controlling in Section 3. Miscellaneous	S S	T R T R T R T R T R T R		- - - - Reg	DIANE M. ADAMS REGISTER OF DEEDS Register of Deeds Stamp & File Number								
Property in Sec.  4. Lot No,  5. Private Claims	S	T Red Plat				1 A	В	C D	E F	е н	i J k	LN	
						2 3	6	5	4	3	2	1	
I, MARINUS MULDER , in a field survey on March 15 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5						4	7	8	9	10	11	12	
						1	18	17	16	15	14	13	
above were in conforman Court of Law; establis expressed below:	Surveyors or by	a Decree of a	7 8	19	20	21	22	23	24				
NOTE: Not more than on this certific	s, all in the same	I in the same town and range, may be recorded			· 1	30	29	28	27	26	25		
A. Description of original	ginal mor	nument and acces	and accessories and/or subsequent restoration:			12	31	32	33	34	35	36	
This corner was was set witness 32 links. Perpetuation: Section 4 in Ma Records, but sh D.C. Crawford a G.L.O. notes fo Oak N 41° W 33 setting 2 1/4"	D.C. ( y 1892 ows no lso sh r F-3	a 4" White Crawford for Crawford in Vocantion Crawformation Crawford	The Tonia Control of the Tonia	County Surage 264 or margin of White Oal	links and rveyor pe f the Ion the Coun k S 89° W	a 2 erfo ia ity : 45	22" rmec Cour Surv	Whited a nty seven	survo Survo rs co	ak N ey in eyors opy o	50° n s of th	E ie	

Description of corner evidence found and/or method applied in restoring or reestablishing corner: THIS 1/4 CORNER FALLS IN AN EAST-WEST FARM FENCE LINE AND TREE ROW. THERE ARE LARGE PILES OF FIELD STONE UP AND DOWN THE FENCE LINE. MEASURED EAST FROM THE SOUTHWEST CORNER OF SECTION 4 TO GET IN THE CORRECT VICINITY. FOUND A LARGE STUMP WEST OF THE MEASURED POSITION THOUGHT TO BE ONE OF CRAWFORD'S 1891 WITNESS TREES. MEASURED 29.7 FEET EAST OF THE STUMP AND STARTED REMOVING STONES. FINALLY GOT DOWN TO GRADE AND BEGAN DIGGING WITH SHOVELS. FOUND 2 1/4" GLAZED CYLINDER WITH STONES AROUND THE BASE ABOUT 8" BELOW SURFACE GRADE.. THE WITNESS DISTANCE TO THE LARGE STUMP MEASURED ABOUT 28.8 FEET TO THE FACE. ACCEPTED THIS AS THE CORNER FOR F-3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set a 3/4" x 36" steel rod with a 2 3/4" cap stamped "Ionia County, P.S. 25863" inside the 1" pipe, sticking 12" above grade with stones piled around and on top of a hill at the Southeast corner of a cultivated field in an old tree row with reer Group Nail & tag in top of 48" Oak Stump S 73° E 20.03 feet P.A. 345 Ionia County Nail & tag Northeast side 3" Cedar S 43° E 18.63 feet Nail & tag East side 36" Oak S 25° W 97.07 feet Date 1/-1-95 Nail & tag Southeast side 12" Cherry S 65° W 38.33 feet Marinus A. Mulder, Chairman T fence post Southwest 1.5 feet

11-13-95