	en e								
LAND CORNER RECORDATION CERTIFICATE									
Filing Requirement of Act 74, Mich. P.A. 1970			~	`	.94	٦.			
For corners in Located in: Corner Code # 1. Public Land Survey T 5N R 6W K-9 T R			REGISTER OF DEFOS	<i>)</i> -	4 DEC 29	RECEIVED FO	SPARESTA		
TR			Defras	}	P1:57	PLO SE	CHISAN		
T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	egister of Deeds Stamp & File Number								
4. Lot No, Recorded Plat									
5. Private Claims	1 ' 2	6	5	4	Э Н	J K 2	1		
	3								
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points		7	8	9	10	11	12		
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points			17	16	15	14	13		
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded		19	20	21	22	23	24		
		30	29	28	27	26	25		
on this certificate.	12	31	32	33	34	35	36		
A. Description of original monument and accessories and/or subsequent restoration: THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR, LUCIUS LYON IN 1827. A A 18" SUGAR N 22° E 5 LINKS AND A 18" SUGAR S 41° W 30 LINKS.	13 l	OD POS	T WAS	SET A	ND WIT	nessei) BY		
THERE IS NO RECORD OF COUNTY SURVEYOR PERPETUATION OF K-9. THE IONIA COUNTY ROAD COMMISSION RECONSTRUCTED AND PAVED MUSGROVE HIGHWAY IN 1964. PLAN INFORMATION IS FOUND ON SHEET NO. 4 OF PROJECT NO. 5 544. THE PLANS CALL FOR AN AXLE SHAFT WITNESSED BY: POWER POLE NORTHEAST 55.44' STEEL FENCE POLE NORTHWEST 41.28' TELEPHONE POLE SOUTHWEST 46.35' SIGN POST SOUTHWEST 37.20'									
B. Description of corner evidence found and/or method applied in restoring or reestablishing FOUND NAIL & TAG AT ROAD SURFACE AT DEPTH OF 12*. FOUND A LARGE STONE. THE AXLE	SHAF	T WAS	ON TH	ie west	r side	ор тн	ie		
STONE. ACCEPTED THE STONE AND AXLE SHAFT AS THE BEST AVAILABLE EVIDENCE OF THE PO	Siti	ON OF	THE O	RIGIN	AL CORI	vek.			
C. Description of monument for corner and accessories established to perpetuate locating the SET A 12" MONUMENT OVER THE TOP OF THE AXLE SHAFT AND STONE WITH A 4" DIAMETER BROWN AND STONE WIT	-					יטוואייע.			
SURVEY MONUMENT - DO NOT DISTURB" WITHESSED BY: NAIL & TAG EAST SIDE 6" ELM N 19° W 61.69' NAIL & TAG EAST SIDE POWER POLE N 33° E 55.56' CENTERLINE 4" STEEL POST N 38° W 41.30' TOP CENTERLINE OF M.B.T. BOX S 56° W 47.42'				Ratified by Peer Group P.A. 345 Ionia County					
Signed by Mariel a mulder para 12-27			Date 10-20-94 Marinus A. Mulder, Chairman						
Signed by Musik a Minda	フ~	90							

BOOK 003 PAGE 167

Surveyor's Michigan License No. ____

MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993