## SURVEY & REMONUMENTATION

## APR 27 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in						****	٠.٠٠		
IONIA	Located In:	Corner Code #			œ		92	2	ריי. מי
(County)					REGISTER OF	3		٤.	) 1 <u>}</u> >
		1			SI	2	AUN	~	95
		İ			inj.	5	₹	(~* 	- 12 C
<ol> <li>Public Land Survey</li> </ol>	T 5N R 7W	E-3			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	$\supset$	22		F.
	T Ř				, H	$\overline{}$	, 0	(C) 30	==
	T R				DEEDS	$\simeq$	70	147	~ 5
		_				اد ال	ယ	177	-665
	TR					•	<u>~</u>	Ş	35
2. Property Controlling	S T R		_					, Fig.	
in Section	S T R	Re	egiste	r of De	eds St	amp &	HIE N	umper	
3. Miscellaneous	STR								
Property in Sec.	STR								
Troporty in Goor	<u> </u>								
d I - c N -	Decarded Diet								
			1.	4 8 4	C D	E F (	<i>∋</i>	JK	L N
5. Private Claims						ļ			
			2	6	5	4	3	2	1
			3			<b>&gt;</b>			<del> </del>
			4	7	8	9	10	11	12
I, <u>MARINUS MULDER</u>	, in a field surve	y on <u>8-3</u> 1994,		′	"	1 '	'0		12.
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points									
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as					17	16	15	14	13
required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points									
Interior, Bureau of Land N	Management or by a decree of a C	with the rules of the Michigan Board o	5 7 f 8	19	20	21	22	23	24
Land Surveyors or by a De	oree of a Court of Law. est	ablished, re-established, monumented		' '	20	"			
re-monumented recovere	ed, found as expressed below:	abilition, to obtabilition, inclination	' 9	ļ					
To mondinarious	a, realize as supresses series.		10	30	29	28	27	26	25
NOTE: Not more than	4 corners, all in the same town	and range, may be recorded	11						
on this certifica			12	23	20	22	24	35	36
011 (1110 001 (1110	201			31	32	33	34	33	30
A. Description of orig	rinal monument and accessorie:	s and/or subsequent restoration:	13	L	<u> </u>	<u>.                                    </u>	L		
THIS CORNER WAS FIRST	ESTABLISHED BY U.S. DEPUTY	SURVEYOR, JOHN MULLETT IN 1830.	A W	OOD PO	OST WA	S SET	WITNES	SED B	ΥA
24" WHITE OAK N 27° W	EST 48 LINKS AND A 12" WHIT	E OAK SOUTH 24 LINKS.							
PERPETUATION: A.C.	SMITH, FORMER IONIA COUNTY	SURVEYOR, PERFORMED A SECTIONAL S	SURVE	Y IN S	SECTION	N 8, D	ECEMBI	ER 5-9	,
1876 RECORDED IN VOLU	ME 1, PAGE 222 OF THE COUNT	Y SURVEYORS RECORDS. SMITH NOTE	D A S	TAKE A	AND ST	ONE FO	R E-3	BUT G	AVE
NO WITNESSES.							2 200	14 550	000000
D.C. CRAWFORD FORMER	IONIA COUNTY SURVEYOR, PERI	FORMED A SECTIONAL SURVEY OF SECT	ION 4	, IN A	APRIL :	22 & 2 nm 53	13, 188 13 MAN	CTATE	UZUZU TUZUZU
IN VOLUME 1, PAGE 364	OF THE IONIA COUNTY SURVEY	FORS RECORDS. CRAWFORD SAID HE FO	ייאר. זאני מאר זאני	THE CO	OKNEK I	COIDITY PUL DI	TOM U.	SAUAS	CUDA MUVI
HE DID FIND OR RE-SET	ON DAGE 119 CRAWFORD NOTED	12" HICKORY N 64° W 67 1/2 LINE	CS AND	O A 8'	HICKO	ORY N	23 1/2	° W 82	2 1/2
LINKS.	ON PAGE 118 CRAWFORD NOIED	12 MICROAL HOT HOT LIE DILL		·	1137010				,
CDAWFORD ALSO PERFORM	ED A SECTIONAL SURVEY IN SI	ECTION 9 ON APRIL 24 & 25, 1884, 1	FOUND	IN VO	DLUME .	1 PAGE	366 (	F THE	
IONIA COUNTY SURVEYOR	S RECORDS. CRAWFORD SAID	IE FOUND THE CORNER (E-3)							
THE IONIA COUNTY ROAD	COMMISSION RECONSTRUCTED	AND PAVED CLARKSVILLE ROAD IN 196	5. P	LAN I	nforma	TION I	IS FOU	ND ON	SHEET
NO 7 OF STATE PROJECT		L FOR A 3/4" IRON WITNESSED BY:							
TELEPHONE POLE SOUTHE									
FENCE POST NORTHEAST	38.92								
SIGN POST NORTHEAST 3									
POWER POLE SOUTHWEST	70.281								
<ul> <li>B. Description of corr</li> </ul>	ner evidence found and/or meth	od applied in restoring or reestablishir	ng cor	ner:					
		more	v 10	<b>"</b> GOT :	- C - C - C - C - C - C - C - C - C - C	97 D37	MAC I	eorne.	
JUST BELOW ROAD SURFA	CE A 1/2" X 18" RE-BAR WAS	FOUND. AT A DEPTH OF 22" A 3/4" NO MORE EVIDENCE. ACCEPTED THE :	3/411 3/411	TOT.TD	DAD A	с тик С тик	DEDDE	יטאטט משידעוזיי	
CORNER.	O A DEPTH OF 42" BUT FOUND	NO MORE EVIDENCE. ACCEPIED THE .	3/4	SOUTE	DAIL M	5 11125	E BALL II.	. 0112	
CORNER.									
C. Description of mor	nument for corner and accesso	ries established to perpetuate locating	the p	ositio	n of the	e corne	er:		
PERFORED 3 / 4 H W 3 CH GG	ATTO CONTROL DATO AND COME & 201	MONUMENT WITH A 4" DIAMETER BROI	M7F C	አኮ ሮሞን	пади	"TONTA	COINT	מונצ עי	VEY
		MONOMENT WITH A 4 DIAMETER BROI	M211 C.	ME DII					
MONUMENT - DO NOT DISTURB" . WITNESSED BY:					Ratif	ied t	y Pe	er Gi	onb
	SIDE 10" WOOD POST N 48° E	47.41'			P.A.	345	Íonia	Cou	nty
NAIL & TAG SOUTH SIDE	RAILROAD TIE POST N 49° W	44.15'							
NAIL & TAG NORTHWEST	SIDE POWER POLE S 30° W 70.	38'							,
NAIL & TAG NORTH SIDE 6" WILLOW CLUMP S 56° E 66.23'					Date	10.	-20	ーフレ	1
					h.p.	A	Mulde	r Mr	jeman
					Matin	us A.	munuu	i, whi	112191611
P.									
			p	Y		3	. A 17	Ť.	
	,					# FAG	16-54	1	
M1	nid a smulch		1-1.	-9.4	6				
Signed by 1/00		Date		- 1					
Surveyor's Michigan Lic	ense No. 25863	FORM AP	PROVED E	BY MICHIG	AN STATE I	BOARD OF I	LAND SURV	EYORS, JA	N. 28, 197
									Y 1-1, 1975