## SURVEY & REMONUMENTATION

## APR 27 1995

Surveyor's Michigan License No.

25863

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 REGISTER OF DEFIUS For corners in Corner Code # Located In: IONIA (County) T5N R 7W 1. Public Land Survey 2. Property Controlling S Register of Deeds Stamp & File Number S in Section 3. Miscellaneous S Т Property in Sec. S \_\_\_\_, Recorded Plat \_ , A BCDEFGHIJKLM Private Claims 2 ī 5 4 3 2 6 3 4 9 10 11 12 7 8 \_ , in a field survey on \_ MARINUS MULDER 3-14\_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the 14 13 17 15 Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points 10 20 21 23 24 mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of 8 22 Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 9 re-monumented, recovered, found as expressed below: 10 30 29 28 27 26 25 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 36 12 31 32 33 35 13 Description of original monument and accessories and/or subsequent restoration: A. THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR, JOHN MULLET IN 1830. MULLETT CLOSED ON THE TOWNLINE 86 LINKS EAST OF THE STANDARD CORNER. MULLETT CALLED FOR A 24" LYNN FOR THE CORNER BUT GAVE NO WITNESSES.

PERPETUATION: FORMER IONIA COUNTY SURVEYOR , A.C. SMITH PERFORMED A SECTIONAL SURVEY IN SECTION 4, OCTOBER 18 & 19 1875, RECORDED IN VOLUME 1, PAGE 136 OF THE IQNIA COUNTY SURVEYORS RECORDS. SMITH DID NOT STATE WHAT THE CORNER (G-1) WAS MARKED WITH BUT HAD 1 WITNESS, BEING A 12" BEECH S 41 1/2° E 63 1/2 LINKS. D.C. CRAWFORD FORMER IONIA COUNTY SURVEYOR PERFORMED MORE WORK IN SECTION 4 T5N-R7W, AFRIL 22 & 23, 1884 RECORDED IN VOLUME 1 PAGE 364 IONIA COUNTY SURVEY RECORDS. CRAWFORD HAS A NOTE FOR G-1 STATING "CORNER RESET" BUT SHOWS NO WITNESSES. THE IONIA COUNTY ROAD COMMISSION RECONSTRUCTED AND PAVED JORDAN LAKE ROAD IN 1967. PLAN INFORMATION IS FOUND ON SHEET NO. 5 OF COUNTY PROJECT C-153. THE PLANS CALL FOR A 1 1/2" BOLT WITNESSED BY A 10" ELM N 82° 30' E 157.70'; TELEPHONE POLE S 69° 30' E 69.05'; BOX ELDER STUMP S 76° W 86.80' AND A 36" ELM N 53° 45' W 105.66'. Description of corner evidence found and/or method applied in restoring or reestablishing corner: AT ROAD SURFACE FOUND A 1/2" ROD AND CAP SET BY PROFESSIONAL SURVEYOR, KEVIN ROOSIEN NO. 31604. AT 0.20' NORTH AND 3" BELOW SURFACE FOUND A 1" PIPE. REMOVED PIPE AND AT A DEPTH OF 16" FOUND LARGE PILE OF STONES BEING AT THE INTERSECTION OF GOODEMOTE ROAD AND JORDAN LAKE ROAD. ACCEPTED THE 1" PIPE IN THE STONE PILE AS THE Ratified by Peer Group PERPETUATED CORNER. P.A. 345 Ionia County Date 10-20-94 Marinus A. Mulder, Chairman Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET A 7/8" X 18" ROD WITH 4" DIAMETER CAP STAMPED "IONIA COUNTY SURVEY - DO NOT DISTURE" OVER THE 1" PIPE WITNESSED BY: NAIL & TAG 14" OAK S 18° E 94.60 NAIL & TAG NORTH SIDE POWER POLE N 58° W 105.15' PHYSICAL CENTERLINE JORDAN LAKE ROAD EAST 23' SOUTHWEST CORNER SECTION 34, T6N-R7W, (7/8" X 18" ROD WITH A 4" DIAMETER BRONZE CAP STAMPED IONIA COUNTY SURVEY MONUMENT) WEST 57.34'. NAIL & TAG NORTH SIDE POWER POLE S 72° E 129.18' NAIL & TAG NORTHEAST SIDE 6" FENCE POST N 73° W 143.78' 100 (13 mil 43

Mulden Date 11-1-94