SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION

Surveyor's Michigan License No. 25863

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

W	Filing Requiren	lent of Act 74, with P.A. 197	U						
For corners in									
IONIA (County)	Located In:	Corner Code #			. 2	-	.	<u> </u>	
(**************************************					938 6	\gtrsim		(**)	\$ 5
Public Land Survey	T_5NR_7W	G-2			REGISTER		ΛŪΝ		54 218
1. Public Land Survey	TR					₹	~	1 13	÷ <u>C</u>
	T R				9 T		2	CD 0	<u> </u>
	T R				E 2	5	0	<u> </u>	
2. Property Controlling					OS .		 		25 27
in Section	STR	Re	gister	of De	eds St	amp &	Falle N	umber	
3. Miscellaneous	SR								
Property in Sec.	S T R								
4. Lot No, F	Recorded Plat		Δ	. 8	O D	5 F (3 H :	ı J K	JA
			۱ ۲			<u> </u>			Ī
			2	6	5	4 9	3	2	1
			3 4		_	_	70	11	10
1, MARINUS MULDER , in a field survey on 3-7 19 9 4				7	8	9	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as				18	17	16	15	14	13
required in the current manual of survey instructions of the United States Department of the					1/	10	10	124	10
Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of				19	20	21	22	23	24
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			9						
re-monumented, recovered	, round as expressed below.		10	30	29	28	27	26	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11						
			12	31	32	33	34	35	36
A. Description of origin	nal monument and accessories an	d/or subsequent restoration:	13 L		<u> </u>	<u>L</u>	[. <u></u>	<u> </u>	ſ
	ESTABLISHED BY U.S. DEPUTY SU AND A 8 BEECH S 35° W 18 LIN	RVEYOR, JOHN MULLET IN 1830	A WOO	D POS	ST WAS	SET W	ITNESS	EED BY	A 9"
FORMER IONIA COUNTY SU IN VOLUME 1, PAGE 364, DID NOT SAY WHAT WAS F THE IONIA COUNTY ROAD	RVEYOR, D.C. CRAWFORD PERFORM 365 OF THE IONIA COUNTY SURV COUND OR IF THE CORNER WAS PER COMMISSION RECONSTRUCTED AND T C-153. THE PLANS CALL FOR	AS FOUND OR SET FOR THE CORNER ED A SECTIONAL SURVEY IN SECTION OF THE	ON 4, DED T HOWN. PI	HAT I	ie foui iforma	ND THE	S FOUR	CORNER ID ON	BUT SHEET
B. Description of corne	er evidence found and/or method	applied in restoring or reestablishing	g corr	ner:					
		LOW PAVEMENT. BELOW 1/2" ROD TE POSITION OF THE STONES AND B							IN
			R	atifia	ri L	Δ.			
				Ratified by Peer Group P.A. 345 Ionia County					
				- 10 Toma County					
				Date 10-20-911					
				Date 10-20-94 Marinus A. Mulder, Chairman					
•			.,,,,,	11112	O. NIG	iger, i	Shairm	a#	
C. Description of mone	ument for corner and accessories	established to perpetuate locating t	the po	osition	of the	corne	r:		
		H A 7/8" X 24" STEEL BAR WITH .						PAMPED	
"IONIA COUNTY SURVEY M WITNESSED BY:	CONUMENT - DO NOT DISTURE"		, 1	2.17.11.1					
NAIL & TAG SOUTHWEST S	IDE 5: ELM N 50° W 48.26'								
CENTERLINE 4" STEEL PO NAIL & TAG NORTHWEST S	ST S 60° W 38.98' IDE 4" ELM N 78° E 33.93'		5009		03		ÀA		
			. • (~~~~	institution.	17		
	<i>i</i>								
Signed by Men	1 a mulder	Date//-	/-	94					

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISEO MAY 14, 1975
REVISEO LANG, 1983