## SURVEY & REMONUMENTATION

## APR 27 1995

## COMMISSION

ŧ	A RITS	へつりがにひ	RECORN	MOITA	CERTIFICATE

LAND CORNER RECORDATION CERTIFICATE													
For corners in	)		OLOME TO		94 Ni	STATI 101 KECEIV							
IONIA (County)	Located in:	Corner Code #		ط: — ح			NOV 22	AN COURT					
1. Public Land Survey	T_5NR7W TR TR	R			DEEDS		P3:40		<u> </u>				
	T R T R			C D -	I O4	O	Tile Mi						
<del>-</del>	gister of Deeds Stamp & File Number												
Property in Sec. S_	T R T R					-							
4. Let No, Reco			1 1	8 (	D D	E F (	ે મા	JK	I M				
3. Thvate Starts			2	6	5	4	3 <b>2</b> 0—	2	1				
I, MARINUS MULDER do hereby certify that under	requirements of P.A. 74, Mich	igan P.A. of 1970, the corner points	4 5	7	8	9	10	11	12				
mentioned in lines 1 and 2 at required in the current manu Interior, Bureau of Land Manag	6 7	18	17 20	16 21	15 22	23	13						
mentioned in lines 3, 4 and 5 a Land Surveyors or by a Decree re-monumented, recovered, for	of a Court of Law; establis	h the rules of the Michigan Board of shed, re-established, monumented,	8 9 10	30	29	28	27	26	25				
NOTE: Not more than 4 cor on this certificate.	ners, all in the same town and	d range, may be recorded	11 12	31	32	33	34	35	36				
A. Description of original r	nonument and accessories an	d/or subsequent restoration:	13		<u> </u>		<u> </u>	<u> </u>					
THE CORNER WITH A STAKE AND STONES BUT GAVE NO WITNESS. F.A. PALMER FORMER IONIA COUNTY SURVEYOR PERFORMED A SURVEY IN THE NW 1/4 OF SECTION 10, SEPTEMBER 20, 1898. PALMER DID NOT SHOW ANY WITNESSES OR WHAT WAS FOUND FOR THE SECTION CORNERS  THE IONIA COUNTY ROAD COMMISSION RECONSTRUCTED AND PAVED JORDAN LAKE ROAD IN 1967 THE PROJECT NUMBER WAS C-153. THE SHEETS FOR THIS SECTION OF ROAD COULD NOT BE FOUND, BUT THE ROAD COMMISSION WITNESS MAP CALLED FOR A NAIL AND BRASS WASHER WITH 9 WITNESS OBJECTS. PROFESSIONAL SURVEYOR, KAY DON FLUKE NO. 18988 RECORDED G-3, MARCH 28, 1972. FLUKE FOUND THE NAIL AND BRASS WASHER AND NOTED THE IONIA COUNTY ROAD COMMISSION WITNESSES STILL APPLY. THIS IS RECORDED IN LIBER 1 PAGE 39 OF ACT 74 RECORDATION CERTIFICATES.													
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  THERE ARE 2 CORNER WITNESSES REMAINING CALLED FOR BY THE ROAD COMMISSION, BEING A HIGHWAY PROJECT MARKER AND A CORNER OF A SCHOOL HOUSE. MEASURED BOTH WITNESS DISTANCES BUT THE BRASS WASHER AND NAIL CALLED FOR WAS GONE. EXCAVATED BELOW AREA WHERE WITNESS DISTANCE CAME AND FOUND A 1 3/4" PIPE 12" DEEP. AT A DEPTH OF 15" FOUND A LARGE POINTED STONE. THE PIPE WAS ON THE WEST SIDE OF THE STONE. THE PIPE AND STONE WERE LOCATED APPROXIMATELY 1 FOOT NORTHEASTERLY OF WHERE THE BRASS TAG AND NAIL WERE SUPPOSED TO BE. ACCEPTED THE POSITION OF THE PIPE AND STONE AS THE PERPETUATED CORNER.													
REPLACED 1 3/4" PIPE WITH DO NOT DISTURB" WITNESSED SOUTHWEST CORNER HOUSE (F SOUTH EDGE 4" CONCRETE RI NAIL & TAC SOUTH SIDE 6"	A 7/8" X 24" STEEL BAR W. BY: ORMER SCHOOL) N 60° E 97.6 GHT OF WAY MARKER S 35° E	46.70'		101" Œ	nia co Ratifi	<b>unty</b> a ed b 345		er Gre Coun	оир ity				
_	1		_			, t. 19	utuef,	unairi	nan				
Signed by Maria	1 a mulde	Date//-/	-4	4	·····								
Surveyor's Michigan License	No. <u>25863</u>	FORM APP	ROVED I	BY MICHIG				EVISED MA	Y 14, 1975 John 1993				