## SURVEY & REMONUMENTATION

## APR 27 1995

## COMMISSION

Surveyor's Michigan License No. 25863

## LAND CORNER RECORDATION CERTIFICATE

i.	Filing Requi	rement of Act 74, Mich. P.	A. 1970						
For corners in	Located In:	Corner Code #			REGISTER	) }	94 NOV 22	SECTIVES.	SIATE SE
Public Land Survey	T5NR_7W TR TR	G-6			OF DEEDS		2 P3:40	FOR ME STATE	Z 0 0 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
in Section S_	T R R T R R T R R R R R R R R R R R R R		Registe	r of D	eeds Si	tamp 8	File N	umbei	r 
4. Lot No, Reco	rded Plat			4 B	C D	E F (	<del>р</del> н і	' J k	( L
5. Private Claims				6	5	4	3	2	1
I, <u>MARINUS MULDER</u> , in a field survey on <u>3-15</u> 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points				7	8	9	10	11	12
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the					17	16	15	14	13
Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				19	20	21	22	23	24
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			10 11	30	29	28	27	26	25
			12	31	32	33	34	35	36
SHEETS FOR THIS SECTION OF OBJECTS FOR G-6. PROFESSIONAL SURVEYOR. DUE CERTIFICATES. ANKROM STATE MATCH THE COUNTY WITNESSES  B. Description of corner evidence of the county of the county witness of	ROAD COULD NOT BE FOUNT NE ANKROM NO. 21265 REVIEW AS FOUNT OF THE WAS FOUNT OF THE WAS FOUND OBJECTS REMAIN STANDING FOUND STONE PILE AND A	A PLATE OF TIN. NO WOOD ST	STER WITNE:  ID IN LIBER  /8" RE-BAR  Abhishing cor	1 PAG AND 1	P CALLS GE 222 FOOK 3 BELOW	S FOR OF AC WITNE:	r 74 R	ESS ECORDA HICH A	ATION ALL
C. Doogrintian of manument	for corner and coorners		<b></b>		of the c				
C: Description of monument for corner and accessories established to perpetuate locating t REPLACED THE 3/8" BAR AND CAF AND 1 1/4" PIPE WITH A 7/8" X 24" STEEL BAR WITH A COUNTY SURVEY MONUMENT - DO NOT DISTURB" WITNESSED BY: NAIL & TAG POWER POLE S 35° W 57.56 FEET. CENTERLINE 4" STEEL POST N 40° W 46.46 FEET. 43.70'. CENTERLINE ROAD SIGN POST EAST 27.95 FEET. NORTHWEST CORNER OF 1 STORY HOUSE FOUNDATION S 45° E 101.80 FEET. NAIL & TAG EAST SIDE UTILITY POLE S 21° W 144.37'				Ratif	r bron ied b	nze cai ov Pe	er Gr Cour	auto	EONIA
				Date 10-20-84 Marinus A. Mulder, Chairman					
						, Ghair GÉ 12	, sakar		
Signed by Marris	a Mulde	Date				u M	GE. F 6	. <b>1</b>	