SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION

Surveyor's Michigan License No. 25863

LAND CORNER RECORDATION CERTIFICATE

| For corners in IONIA (County) | Located in: | Corner Code # | | GISTER OF C | | NIN 22 | IONIA COU | ATE SE MIC | |
|---|---|--|--|---|--|---------------------------|------------------------|------------|--|
| 1. Public Land Survey | T5N R <u>7W</u> T R T R | G-7 | | DEEDS | ð | P3:40 | 13 m | in E | |
| Property Controlling in Section Miscellaneous | STR STR | | gister of Deeds Stamp & File Number | | | | | | |
| Property in Sec. | S T R | | | | | | | | |
| | lecorded riat | | 1 A | 3 C D | F F | G H | I J K | L | |
| | | | 1 1 | 5 5 | 4 | 3 | 2 | 1 | |
| | | | 3 | 7 8 | 9 | 10 | 11 | 12 | |
| I, MARINUS MULDER, in a field survey on 3-15 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points | | | | | | | | 12. | |
| | | vith regulations and rules therefore as the United States Department of the |] ' | 8 17 | 16 | 15 | 14 | 13 | |
| | | urt of Law and/or that the corner points with the rules of the Michigan Board of | 7 - 8 1 | 9 20 | 21 | 22 | 23 | 24 | |
| | cree of a Court of Law; estall, found as expressed below: | blished, re-established, monumented, | 9 — | | <u> </u> | | | <u></u> | |
| NOTE: Not more than 4 | corners, all in the same town a | and range, may be recorded | 10 3 | 0 29 | 28 | 27 | 26 | 25 | |
| on this certificate. | | | 12 3 | 1 32 | 33 | 34 | 35 | 36 | |
| A. Description of origin | nal monument and accessories | and/or subsequent restoration: | 13 | | | 1 | | <u> </u> | |
| RECORDS. NO WITNESSE THE IONIA COUNTY ROAD SHEETS FOR THIS SECTION OBJECTS FOR G-6. PROFESSIONAL SURVEYOR. | S WERE GIVEN. COMMISSION RECONSTRUCTED AN ON OF ROAD COULD NOT BE FOUN DUANE ANKROM NO. 21265 REC | .876 RECORDED IN VOLUME 1 PAGE 216 ED PAVED JORDAN LAKE ROAD IN 1967. ED. THE ROAD COMMISSION MASTER WITH CORDED G-6, JUNE 1977, FOUND IN LIFE FOUND AND HE RAISED IT WITH A 3/6 | THE TNESS | PROJECT MAP CALI PAGE 222 | NUMBER LS FOR | WAS C 5 WITN T 74 R | :-153. ESS ECORD | | |
| B. Description of corne | er evidence found and/or metho | d applied in restoring or reestablishing | corner | : | | | | | |
| | | BELOW BAR FOUND 1 1/4" PIPE 19" DESTUATION OF THE ORIGINAL CORNER PO | | | OF PIPE | FOUND | PILE | OF | |
| REPLACED THE 3/8" BAR COUNTY SURVEY MONUMENT SOUTHWEST CORNER OF HO CALLS FOR 121.75 FEET) | AND CAN AND 1 1/4" PIPE WIT - DO NOT DISTURB" WITNESSE | established to perpetuate locating the A 7/8" X 24" STEEL BAR WITH A 4D BY: | " DIAM | eter bro | ONZE CA | P STAM AD COM | MISSIC | NC | |
| NORTHEAST CORNER OF 4' X 4' PAD ON UTILITY SERVICE RISER BOX S 59° W 55.12 FEET. NAIL & TAG SOUTHWEST SIDE 26" CHINESE ELM N 28° E 112.60 FEET. NAIL & TAG SOUTH SIDE 16" MAPLE N 75° E 67.88 FEET. | | | | Ratified by Peer Group P.A. 345 Ionia County | | | | | |
| | | | Date 16-20-94 Marinus A. Mulder, Chairman | | | | | | |
| Signed by Man | il a mulcle | Date () | | (3 m | ce 12 | \$ | | | |
| originous by | | | | | | | | — | |

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971