DEC 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 003 PAGE 200

For corners in IONIA (County)

STATE OF MICHIGAN
IONIA COUNTY
RECEIVED FOR RECORD

10 OCT 95 4:06 P.M.

DIANE M. ADAMS
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

		Located In:		Corner Code #
1. Public Land Survey		T 5N	R 7W	K-13
		T	R	
		T	R	
		T	R	
2. Property Controlling	S	T	R	
in Section	S	T	R	
3. Miscellaneous	S	T	R	
Property in Sec.	S	T	R	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

I, MARINUS MULDER, in a field survey on JULY 27 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR JOHN MULLETT IN 1830. A WOOD POST WAS SET WITNESSED BY A 15" SUGAR N 40 1/2° E 53 LINKS AND A 18" SUGAR N 27° W 21 LINKS.
PERPETUATION: D.C. CRAWFORD FORMER IONIA COUNTY SURVEYOR PERFORMED A SURVEY OF SECTION 35 FOUND IN VOLUME 3, PAGE 40 OF THE IONIA COUNTY SURVEYORS RECORDS. NO DATE WAS GIVEN. CRAWFORD SAID "OLD CORNER STONE AS USED" BUT GAVE NO WITNESSES.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
EXCAVATED ROAD INTERSECTION AND FOUND LARGE POINTED STONE 6" DEEP WITH BROKEN CROCKERY AT THE BASE OF THE STONE. ACCEPTED THE STONE AS THE CORRECT POSITION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
SET A 3/4" X 24" STEEL ROD WITH A 2 3/4" DIAMETER CAP ON THE NORTH SIDE OF THE STONE WITNESSED BY:
NAIL & TAG NORTH SIDE POWER POLE S 50° W 95.85 FEET
NAIL & TAG SOUTH SIDE POWER POLE N 53° W 70.48 FEET
NAIL & TAG WEST SIDE POWER POLE N 35° E 46.12 FEET
NAIL & TAG SOUTHEAST SIDE POWER POLE N 44° E 29.62 FEET
NORTHEAST CORNER SECTION 2, T4N-R7W WEST 29.33 FEET, 1/2" ROD NEXT TO STONE & BROKEN BRICK

Peer Group
P.A. 345 Ionia County

Date 9-27-95
Marinus A. Mulder, Chairman

Signed by Marinus A. Mulder Date OCTOBER 2, 1995

Surveyor's Michigan License No. 25863

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993