FEB 1 8 1994

## REMONUMENTATION

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Require	Filing Requirement of Act 74, Mich. P.A. 1970			<b>9</b>
Ionia	Landard to	0 0 1 11	ł	COMP.	33
(County)	Located In:	Corner Code ##		K Fais	
1 Dublic Land Comme	T AN D EW	<i>a</i> 7		2,3	27
Public Land Survey	T <u>6N</u> R <u>5W</u> T R	G-7		00	.₩ <u>⊆</u>
	T R			DEEDS OFFEDS	P1:1
	T R			° \$	AN
2. Property Controlling	S T R			•	<b>.</b> (⊃. <b>4</b>
in Section	S T R		İ		
3. Miscellaneous	S T R		Register of	Deeds Stamp	& File Number
Property in Sec.	S T R,				
4. Lot No.	, Recorded Plat				
				CDEF	6 H I J K L M
			26_		<del></del>
			3		
. Manadanna Mallalan	To 1	20	4	<del>                                      </del>	10-11-12-12-1
	_ , in a field survey on <u>July ?</u> requirements of P.A. 74, Michigan P.A. o		entioned		<del>                                     </del>
	in conformance with regulations and		ed in the	17-16-	15 14 13
	structions of the United States Department				<del>                                     </del>
	of a Court of Law and/or that the corner with the rules of the Michigan Board of			20-21-	22 23 24
Court of Law; established,	re-established, monumented, re-ma				<del></del>
expressed below:			10 -30-	29 28	27-26-25
	corners, all in the same town and	d range, may be recorde	1 1		<del>                                     </del>
on this certificate	e.		12 31-	32-33-	34 35 36
A. Description of origina	Il monument and accessories and/	or subsequent restorati	13 <u>LL.</u>	<del></del>	
	rst set by U.S. Deputy S	*		a boow A	ost was set
1890 & 1891. His the County Surveyor	C. Crawford former Ionia witness notes are found rs copy of the G.L.O. no	as marginal note otes. Crawford's	s next to the : witnesses for	respective G-7 are:	corner on 1890,
	W 46 links and 12" Blace			awford use	d 2 1/4"
	zed clay tile cylinders in May of 1981 recovered			10001-	arrantation
	d finding a 2 1/4" diame				
	This corner is recorded evidence found and				
eround 5/8" rod and and replaced the 5	cap next to a 2 1/4" cl /8" rod and cap with a 3	RAY CYLINGER. AC	cepted this as	the posit	TOIL TOL G-/
end repraced the of	, o loc ala cap widi a c	D/4 A JO SCECE.	rod and cap.		
□. Description of monume	ent for corner and accessories est	tablished to perpetuate	locating the position	of the corner:	
	teel rod and 2 3/4" diam				
√itnessed by:		occur oup bounpou	round comici	1.0. 2500	
	de 30" stump N 5° E 29.8	86! (This could be	ossibly be one	of Crawfor	rale 1890
vitnesses)	ie 30 scump N 3 E 29.0	o (mis como po	pasinity be offe	OI CLAWIO.	LU S 1090
√ail & tag West sid √ail & tag Northeas	de fence post S 04° W 43 st side 16" Hickory S 48 st side 14" Oak S 27° E	s° E 94.98'			
-					
-igned by OM.C.	nd a mich	Le ·	October 28,19	10.2	
igned by		Date	OCCUDED 20,15	190	
-urveyor's Michigan Licens	ie No25863				

UNER 003 PAGE 75

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983