REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

REMONUMENTATION

CONTRIBUTION

CONTR For corners in TONIA 1. Public Land Survey T6N R6W 2. Property Controlling S S Register of Deeds Stamp & File Number in Section 3. Miscellaneous S Property in Sec. \$\_ \_, Recorded Plat \_\_ D F L 1 5. Private Claims \_\_ 2 2 6 5 4 3 7 3 4 0 7 R 10 11 12 MARINUS MULDER , in a field survey on OCTOBER 3 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as ó 18 17 16 15 14 13 required in the current manual of survey instructions of the United States Department of the 7 Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points 21 22 24 mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of 8 19 20 23 Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, Q re-monumented, recovered, found as expressed below: 10 30 29 28 27 26 25 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 35 36 31 32 13 Description of original monument and accessories and/or subsequent restoration: THIS CORNER WAS FIRST SET BY U.S. DEPUTY SURVEYOR, LUCIOUS LYON IN 1827. A WOOD POST WAS SET WITNESSED BY A 18" LYNN N 55° E 5 LINKS AND A 20" BEECH S 32° W 22 LINKS. PERPETUATION: D.C. CRAWFORD FORMER IONIA COUNTY SURVEYOR PERFORMED A SECTIONAL SURVEY IN SECTION 11, DECEMBER 6-8, 1888 FOUND IN VOLUME 1, PAGE 470 OF THE COUNTY SURVEYORS RECORDS. CRAWFORD STATES HE FOUND THE OLD 1/4 POST. CRAWFORD DOES NOT STATE WHAT WAS SET. I, MARINUS MULDER, FOUND A POINTED STONE WITH SMALLER STONES AT ITS BASE JUNE OF 1983 WHICH IS RECORDED IN LIBER 2 PAGE 226 OF ACT 74 RECORDS. I SET A 5/8" ROD AND CAP NEXT TO THE STONE, AND TOOK 4 WITNESS. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND THE 5/8" ROD AND CAP NEXT TO THE POINTED STONE AS SET IN 1983 AND ACCEPTED THIS AS THE CORNER. THE STONE WAS AT A DEPTH OF 10".

C.	Descr	iptio	n of	f monu	men	t for c	orne	r and	accessorie	s est	tablished	to perpeti	uate loca	atin	g the p	ositi	ion o	f the	COTTK	ar:	
SET	A 3/4"	X 2	24 "	STEEL	BAR	WITH	A 2	3/4"	DIAMETER	CAP	STAMPED	"P.L.S.	25863"	IN	PLACE	OF	THE	5/8"	ROD	AND	CAP.
WITON	PCCDD	DV.																			

NAIL & TAG SOUTHWEST SIDE 18" WALNUT N 50° W 41.38'

NAIL & TAG SOUTH SIDE 16" WALNUT N 73° W 62.51' NAIL & TAG WEST SIDE 24" MAPLE NORTH 36.79'

NAIL & TAG WEST SIDE 14" WALNUT SOUTH 27.31'

Ratified by Peer Group P.A. 345 Ionia County

	,			Date 12-22-94  Marinus A. Mulder, Chairman				
Signed by	marind a	milden	Date	12-27-84				
Surveyor's N	lichigan License No2	5863		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971				