POLONY REMONUMENTATIO

DEG 0 2 1997

LAND CORNER RECORDATION CERTIFICATE

COMMISSION:

Filing Requirement of Act 74, Mich. P.A. 1970

ITREE 003 PAGE 358

| For corners in !ONIA | Located In: | Corner Code # | | | 5 | IATE O | F MICH | IGAN | | |
|--|---|---|-------------------|----------|-----|-----------------|----------------------------|--------|----|-----|
| (County) 1. Public Land Survey | т6 <u>N</u> R7 <u>W</u> т R | | | | | ECEIVE | A COUN D FOR 1 7 3:5 | RECORD | | |
| Property Controlling in Section Miscellaneous Property in Sec. | T R R S T R S T R S T R R S T R R S T R R S T R R S T R R S T R R S T R R R R | | Regis | | | REGIST ds St | | File N | | |
| 4. Lot No, Recorded Plat | | | | ۱ ^ ۲ | B C | D E | F G | [| ļ | 1 |
| I, MARINUS MULDER , in a field survey on 6.13 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in the line of the survey were in conformance with regulations and rules therefore as required in the line of the laterior Bureau of Land | | | | 2 | 6 | 5 | 4 | 3 | 2 | 1] |
| | | | | 3 4 | 7 | 8 | 9 | 10 | 11 | 12 |
| | | | | 5 - | 18 | 17 | 16 | 15 | 14 | 13 |
| lines 1 and 2 above were in conformance with regulations and rules therefore the lines of Land current manual of survey instructions of the United States Department of the Interior, Bureau of Land current manual of survey instructions of the United States Department of the Interior, Bureau of Land Survey in the lines 3, 4 and 5 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 Management or by a decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as Court of Law; established, re-established, monumented, re-monumented, recovered, found as | | | 7 8 | 19 | 20 | 21 | 22 | 23 | 24 | |
| Court of Law; established expressed below: | ed, le-establishes, | | | 9 10 | 30 | 29 | 28 | 27 | 26 | 25 |
| NOTE: Not more than 4 cor on this certificate. | rners, all in the same town | and range, may be recorded | | 11 12 | 31 | 32 | 33 | 34 | 35 | 36 |
| A. Description of original monu THIS CORNER WAS FIRST ES WAS SET WITNESSED BY A | | subsequent restoration: PTY SURVEYOR JOHN MULLETT IN 1831, NKS AND A 16" SUGAR S 50° W 30 LINKS | A WOOD POST S. | 13 | L | J | L | | | |

PERPETUATION: THERE ARE NO RECORDED SURVEYS BY THE IGNIA COUNTY SURVEYOR FOR E-9.

FORMER STATE HIGHWAY U.S. 16 CROSSES THIS CORNER IN AN EAST-WEST DIRECTION. THIS HIGHWAY WAS CONSTRUCTED IN 1928. THE IONIA COUNTY

THE MICHIGAN DEPARTMENT OF TRANSPORTATION SECTION CORNER REFERENCE CARD, SIGNED BY SURVEY CHIEF JOHN SPENCER, JULY 1967, SHOWS A PIPE ROAD COMMISSION DOES NOT HAVE ANY WITNESSES FOR E-9. FOUND AT THE SURFACE OF THE PAVEMENT OF GRAND RIVER AVENUE (U.S. 16). SPENCER WITNESSED THE CORNER AS FOLLOWS: CORNER FENCE POST NORTH 50.89 FEET, NORTHWEST CORNER CONCRETE HEADWALL N 55° E 36.08 FEET, SOUTHWEST CORNER CONCRETE HEADWALL S 55° E 34.60 FEET, NAIL & TAG IN TELEPHONE POLE S 5° W 49.11 FEET.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: AT THE POSITION OF E-9 THERE IS 1 OF SPENCER'S WITNESSES REMAINING BEING THE CONCRETE HEADWALL NORTHEAST. THERE ALSO IS A FENCE RUNNING SOUTH. THE HEADWALL IS IN DISREPAIR AND SOMEWHAT TIPPED ON AN ANGLE. MEASURED FROM THE SOUTHWEST CORNER OF APPROXIMATELY WHERE IT WOULD BE AND INTERSECTED THE PAVEMENT ON THE EXTENSION OF THE SOUTH FENCE LINE. THERE WAS NO VISIBLE CORNER AT THE ROAD SURFACE. EXCAVATED THRU 1 1/2" OF BITUMINOUS AND FOUND RAILROAD SPIKE.

EXCAVATED THRU BITUMINOUS AND FOUND 1/2" PIPE IN OLD CONCRETE ROAD. REMOVED 1/2" PIPE 12" LONG BUT FOUND NO OTHER EVIDENCE BELOW PIPE.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: REPLACED THE 1/2" PIPE WITH A 7/8" STEEL ROD WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY 25863" WITNESSED BY:

> MARINUS & MULDE LAND SURVEYOR No. 25853 TO CAME OF

CENTERLINE OF 3" STEEL FENCE POST S 27° W 108.42 FEET

NAIL & TAG

EAST SIDE POWER POLE S 9° E 32.37 FEET

NAIL & TAG

SOUTH SIDE 40" ASH N 79° E 201.44 FEET

NAIL & TAG

Surveyor's Michigan License No. ___

SOUTH SIDE 26' MAPLE N 67° W 123.18 FEET

CENTERLINE OF PAVEMENT 0.4 FEET SOUTH

Raiffied by Pee, Group F.A. 545 Ionia County

Nate 9-24-97

Marinus A. Mulder, Chairman

Signed by Maris a . mulcle

25863

10-3-97 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYURS, JAN. 28, 1971

REVISED MAY 14, 1975 Revised Jan., 1983 Adapted for word processive March, 1993