LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 4 PAGE 103

For corners in IONIA (County) SECTION

Located In: Corner Code #

STATE OF MICHIGAN
IONIA COUNTY
RECEIVED FOR RECORD

23 NOV 99 3:03 P.M.

DIANE M. ADAMS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey		T6 N	R7 W	G-10
		T	R	
		T	R	
		T	R	
2. Property Controlling in Section	S	T	R	
	S	T	R	
3. Miscellaneous Property in Sec.	S	T	R	
	S	T	R	

4. Lot No. _____ , Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

I, MARINUS MULDER, in a field survey on JUNE 16 19 99, do hereby certify that under *requirements of P.A. 74, Michigan P.A. of 1970*, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions *of the United States Department of the Interior*, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the *Michigan Board of Land Surveyors* or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: **Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:
THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR JOHN MULLETT IN 1831. A WOOD POST WAS SET WITNESSED BY A 10" BEECH S 62° W 22 LINKS AND A 7" BEECH S 55° E 17 LINKS.

PERPETUATION: THERE ARE NO RECORDED COUNTY SURVEYS FOR SECTIONS 27 OR 28.

THE MICHIGAN DEPARTMENT OF TRANSPORTATION HIGHWAY PLANS FOR I-96 CALL FOR G-10 TO BE ON THE SOUTH RIGHT OF WAY LINE OF I-96.

THE IONIA COUNTY ROAD COMMISSION IN THE SECTION CORNER INDEX SHEETS CALLS FOR A 1/2" PIPE. THE WITNESSES ARE ILLEGIBLE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
G-10 IS LOCATED IN JORDAN LAKE ROAD ON THE SOUTH SIDE OF THE BRIDGE SPANNING I-96. FOUND A MONUMENT BOX 4" BELOW THE PAVED SURFACE WITH A 1" SOLID SHAFT IN THE BOX. SET A 4" DIAMETER CAP ON THE 1" SHAFT IN THE MONUMENT BOX.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1" SOLID SHAFT WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY SURVEY MONUMENT -P.S. 25863" SET IN A MONUMENT BOX (NOTE: RAISED BOX TO ROAD SURFACE) WITNESSED BY:

SOUTHEAST CORNER CONCRETE BRIDGE ABUTMENT		N 40° W 25.92'
SOUTHWEST CORNER CONCRETE BRIDGE ABUTMENT		N 42° E 25.95'
N&T	CENTER GUARD RAIL POST	S 50° W 22.61'
N&T	CENTER GUARD RAIL POST	S 50° E 23.06'

Signed by Marinus A. Mulder Date 11-3-99

Surveyor's Michigan License No. 25863

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

Ratified by Peer Group
P.A. 345 Ionia County

Date August 18, 1999
Marinus A. Mulder, Chairman

STATE OF MICHIGAN
MARINUS A. MULDER
PROFESSIONAL SURVEYOR
No. 25863