BUHVEY & ONUMENTATION

DEC 1 & 1996

For corners in

IONIA

COMMISSION

Located in:

LAND CORNER RECORDATION CERTIFICATE

Filing Requirem

	***		777	
LIBER	J	PAGE	270	

g Requirement of Act 74, Mich. P.A.	1970				
		STA	NTE OF	MICH	HIGAN
			IONIA	COUN	YTY
Corner Code #		REC	EIVED	FOR	RECORD

							l l										
1. Public Land Survey T6 N R 7W K-8						24 OCT 96 3:57 P.M.											
1. Public Land Survey T6 N R 7W T R				K-0	<u>K-8</u>						DIANE M. ADAMS						
		T					_					F DEED	9				
	_	<u> </u>	_ R				_										
2. Property Controlling in Section		- T					-										
							- Reg	iste	r of D	eeds S	tamp	& File i	Numbe	r			
Property in Sec. S							\$						***************************************	<u> </u>			
4 tothin Bar	arded Plat																
4. Lot No, Rec 5. Private Claims	Olueo ciat							1 1	A B	CD	E F C	∋ H (JK	L M			
	-							2	6	5	4	З	2	1			
			٠.					3				10	,,	10			
 MARINUS MULDER do hereby certify that und 							te montioned in	5	7	8	9	10	11	12			
lines 1 and 2 above we	ere in conf	ormance v	with reg	gulations a	nd rules th	erefore as r	equired in the	6	18	17	16	15	14	13			
current manual of survey Management or by a deci								7		''		,					
above were in conformar Court of Law: establis	ice with the	e rules of	the Mich	nigan Board	d of Land S	urveyors or b	y a Decree of a	8	19	20	21	22	23 (> 24			
expressed below:	sileu, ie-e	staunsneu	i, intonu	illieliteo, i	e-monumen	ileo, lecovei	eu, louila as	9		<u> </u>							
NOTE: Not more than 4	corners, all i	is the same	town an	d range, ma	v he recorded			10	30	29	28	27	26	25			
on this certificate	-			u tungo, me	, 40 .000.000			11		-							
A. Description of original mo	oument and	nannaan ina	andlar aub	engungi raeti	aralion:			12	31	32	33	34	35	36			
A. Description or original inc	त्त्रात्याच्यात् स्थातः	rressoues s	auntai 200	sednem 1621	nacivii.		;	13	L		******						
THIS CORNER WAS FIRST	ESTABLISHI	ED BY U.S.	DEPUTY	SURVEYOR	JOHN MULL	ETT IN 1831.	A WOOD POST V	/AS	SET WI	TNESSE	D BY A:	6" BLAC	K ASH	N 44°			
E 11 LINKS AND A 8" BLAC																	
THERE IS NO RECORDED C	UUNIY SUR	IVEYOR INF	URMATI	IUN FUR K-8		74 BEGGBBE			urior		DAILDO		/F :14 ! F	147 6 37			

PROFESSIONAL SURVEYOR RON.HELSEL NO. 18994 RECORDED K-8 JANUARY 1974, RECORDED IN LIBER 1 PAGE 96. HELSEL SET A RAILROAD SPIKE HALFWAY AND ON LINE BETWEEN THE NORTHWEST CORNER OF SECTION 24 AND THE SOUTHWEST CORNER OF SECTION 24. HELSEL TOOK 3 WITNESSES.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND HELSELS SPIKE IN HARWOOD ROAD. EXCAVATED ROAD WITH A BACKHOE AND 2 FEET NORTH AND 2 FEET WEST FOUND A LARGE PILE OF STONES IN A CIRCLE (1 NICELY SHAPED CUT STONE) 31" DEEP. ACCEPTED THE STONE PILE AS THE PERPETUATION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET A 30" LONG ALUMINUM MONUMENT WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY 25863" OVER THE CENTER OF THE STONE PILE.

WITNESSED BY:

NAIL & TAG POWER POLE N 90° E 41.15' . NAIL & TAG WEST SIDE 40" ASH S 15° E 83.67' NAIL & TAG SOUTHEAST SIDE 22" LOCUST \$ 63° W 34.17" NAIL & TAG SOUTH SIDE 42" MAPLE CLUMP N 60° W 42.72'

Ratified by Peer Group P.A. 345 Ionia County

9-26-96 Marinus A. Mulder, Chairman



Surveyor's Michigan License No.