LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	6
1. PUBLIC LAND SURVEY 5	T. 6 N., R. 7 W.	3-6	jonia
2. PROPERTY CONTROLL- 5 ING IN SECTION	,T. 6 N., R. 7 V.		Jon.
3, MISCELLANEOUS PROPERTY IN SECTION	,T N. R E. W.		
4. LOT NO , RECO	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 27 April 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1921, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Denosiasion of course eviden	as found and/as mothed and	diad in marraina as as assell	:- b :
B. Description of corner evidence FOUND BOAT DAVID HWY, & E	SPIKE IN	-	
Information fuen	sered by Bad	Snitt	
C. Description of monument for	corner and accessories e	stablished to perpetuate loca	ting the position of the corner:
NIZE,	79.0, 12 M	PAPLE P.K. NAIL S	Beass Washer
N 36°W	61.14 POWER	POLE PRIMAR &	Brass Carles
			Chart Correct to
SIGNED BY		DATE	une 197/
SURVEYOR'S MICHIGAN REGI	STRATION NO.		(SEAL)
FOR STATE AND UNITED STA	TES AGENCIES:		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	MICHIGAN REGISTERED LAN	DATE	
			(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _