## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	2 T. 6 N. R. 7 V.		Jonia E
2. PROPERTY CONTROLL- ING IN SECTION	2 ,T. 6 N. R. 7 V.		u
	,T		
4. LOT NO , RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
restored as expressed below of survey instructions of the court of law. Furtherms	w and in conformance with regular that the corner points m	It if it is a circles on index l, re-established, monumente clations and rules therefore a the Interior, Bureau of Land entioned in lines 3, 4 and 5	P.A. 74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contra or, by a Decree of a Court of
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner en  FOUND E  HWY, INFORMA	vidence found and/or method a BOAT SPIKE IN I TOW FURWISHED I	pplied in restoring or re-estal  WIERSECTION  P  By COUNTY ROAD CO	polishing corner:  HAZWOOD & DAVID  WMM.
N45°W 3 577°W 8 560°W 4 568E 66	HOD' NOON FA	DOF 12" C.M.	in & Beass Washer) P BCE (Fillan & Beass Wikipe)
SIGNED BY		DATE	
0.01.12	REGISTRATION NO.		(SEAL)
FOR STATE AND UNITE			
SIGNED BY	CHIEF OF SURVEY PARTY		
APPROVED AND SIGNED	BYMICHIGAN REGISTERED	LAND SURVEYOR DATE	(SEAL)