SURVEY & REMONUMENTATION

OCT 1 1 1994

REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 LINER 003 PAGE 100

	92	EC 2
LOUNT PY		RECEIVED F
33	-6	A COUNTY OF THE
), Oden	70	*****
EDS EDS	P3:53	S 2
٥	\mathcal{C}_{i}	ã∺ "

Ionia (County)	Located In:	Corner Code ##		DISIE SAMO		EAT.
Public Land Survey	T <u>6N</u> R 8W T R	<u>I~1</u>		M. O	-6 F	F MICH
· .	T R			DEEDS	2: 5.	NAD N
Property Controlling in Section	S T R S T R			,	W 100	
3. Miscellaneous Property in Sec.			Register o	of Deeds Stam	ıp & File Num	ber
4. Lot No, , i	Recorded Plat	11.14	A	a C D E F	= англ	KLM
5. Private Claims	,		2	6-5-4	3-2-	
		1 05 00	4	7 8 9	-10-11-	12
do hereby certify that under re	, in a field survey on <u>Oct</u> quirements of P.A. 74, Michigan P.A. n conformance with regulations an	of 1970, the corner points ment	tioned 6 1	8 17 16	;—————————————————————————————————————	13
current manual of survey instr Management or by a decree of	ructions of the United States Depart a Court of Law and/or that the corne ith the rules of the Michigan Board o	tment of the Interior, Bureau of er points mentioned in lines 3, 4	fLand 7 and 5 8 1	9 20 21	22-23-	24
Court of Law; established, expressed below:	re-established, monumented, re-r	monumented, recovered, four	nd as 9 103	30 29 28	32726-	25
NOTE: Not more than 4 con this certificate.	corners, all in the same town ar	nd range, may be recorded	12 -3	32 33	34-35-	36
A. Description of original	monument and accessories and	d/or subsequent restoration	13 n:	 		1

This closing corner was first set by U.S. Deputy Surveyor, John Mullett in 1830. wood post was set 47 links West of the standard corner witness by: 9" White Oak S 27° E 1/4 links and 8" White Oak S 8° W 52 links.

Perpetuation: D.C. Crawford former Ionia County Surveyor performed a sectional survey in Section 3 on June 4.5 & 6 of 1888. He states that he found all the original stakes on the town line. This survey is found in Volume 1 page 476 of the Ionia County Surveyors Records. He does not state what was set & he gave no witnesses.

(See back)

For corners in

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Excavated road bed with a backhoe and found a large stone 16" deep, 30.82' West of a stone which was found for I-13, T7N-R3W. Accepted this as the corner and set a 3/4" x rod and cap next to stone. Also found a T iron in a 2" pipe located 0.60' East and 0.45' South of the 3/4" rod next to stone.

Ratified by Peer Group P.A. 345 Ionia County

4-20-94000 Date Marinus A. Mulder, Chairman

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 3/4" x 24" rod with a 2 3/4" diameter cap stamped "P.L.S. 25863" next to stone witnessed by:

Square nail in power pole N 8° W 77.10'

Nail & tag Northeast side 26" Elm S 55° E 64.12'

Nail & tag Northwest side 8" Maple N 60° E 66.75' Nail & tag Southeast side wood post S 45° W 36.57'

Southeast corner of Section 34 T7N-R8W East 30.82' (3/4" steel rod with a 2 3/4 diameter cap stamped P.L.S. 25863 next to stone)

=Signed by	Merris	a.	Me	Illa	Date	4-21-	
				· •		the state of the s	

N. 1/4 COR.

SEC. 3.

TGN-R8W

FOUND

T" IRON

2.27'

S89°-13'-22"W 263109'

S. LINE SEC. 34

T7N-R8'

SEC. 34, T7N-R6W

CENTERLINE RD.

N.E. COR.

SEC. 3, T6N-R8W

SEC. 3, T6N-R8W

SEC. 34, T7N-R6'

CENTERLINE RD.