LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF-:	LOCATED	IN -:	CORNER CODE NUMBER	, 12
1. PUBLIC LAND SURVEY_	<i>1</i> 7_ т7_	N. R. 5 V.	5-0	
2. PROPERTY CONTROLL- ING IN SECTION—	17, _{T.} 2	N. R.5	5-0	
3. MISCELLANEOUS PROPERTY IN SECTION -	,T	N. S., R E. W.		
4. LOT NO, RECORDED PLAT				
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 44645 // 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on August 11, 1974, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:				
A. Description of original monument and accessories and/or subsequent restoration:				
Found I" I eon Rod Intersection of Plain and News				
Steerts in Village of Muie				
_			h. Dept. of Sta	,
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
N. 60° E.	64.68	14" Ash		
S 48° E. 4	41.0 7	Elephone Pa	Ble	
S 48° E. 4 S.47° W. 5	5.78 12	"MAPLE		
N. 79°W 3	8.8 S.A	E. CORNER	of 2'X2' Brick Pillar	
S. 60° E. 53	3.65 26	"OAK		
SIGNED BY			DATE	
SURVEYOR'S MICHIGAN	REGISTRATIO	N NO		(SEAL)
FOR STATE AND UNITED STATES AGENCIES:				
SIGNED BY	CHIEF OF	SURVEY PARTY	DATE	
APPROVED AND SIGNED BY DATE DATE				
				(SEAL)