SURVEY & REMONUMENTATION

FEB 1 8 1994

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

For o	corners in	MISSION FIII	ng Requiren	nent of Act 74, Mich.	P.A. 1870	e	7 2	j J	χ. Τι . (ρ	
_IC	ONIA (County)	Located I	n:	Corner Code ##		SIB3) ایران	2	FOR	
1 F	Public Land Survey	T 7N	R_6W_	D=13		EX.				
1, 1	ublic Luna Gui Voy	Т	. R			₽ . 2.2		1		
			. R . R			OFFIDS				
	Property Controlling	s T	. R			\$	Ü	<u>ئ</u> ر		
	n Section Miscellaneous	S T S T			Registe	er of Deeds	Stamp &	k File N	umber	
F	roperty in Sec.	\$ T	. R							—
4. L	.ot No,	Recorded Plat				A B C [) E F (a H L	J K	L M
5. F	rivate Claims					65	4	_ 3		_{
					3					+
i N	Marinus Mulde	⊇r in a field survey or	ser	otember 9 , 1993	, 5	7 - 8	9-	10-1	-11	-12
dohe	ereby certify that under r	requirements of P.A. 74, N	/lichigan P.A. of	1970, the corner points me rules therefore as require	ntioned 6] 18		—15——	_14	-13-
curre	nt manual of survey ins	tructions of the United S	States Departm	ent of the Interior, Bureau	of Land 7					+
above	e were in conformance	with the rules of the Mich	nigan Board of L	oints mentioned in lines 3, and Surveyors or by a Dec	ree of a	— 19—— 20 	21	_22	_23	-24
Court	t of Law; established, essed below:	re-established, monu	mented, re-mo	numented, recovered, fo	und as	-3029	28	_27	_26	25
		corners, all in the sa	me town and	range, may be recorde	ed ¹¹					+
	on this certificat	e.			12 i	-3 ¹ 13 ²	33	-3 4	_35	-36
Α. [Description of origina	al monument and acce	essories and/	or subsequent restorati						
In J in L B. (No exis exca	iber 2 page 365 Description of corner 1936 witness to ting P.I's and vated but no st	set this corne 5. evidence found and/ rees remain. The position of tone found. The	or method ap he road st f the corr e position	Le proportinate replied in restoring or restationing on Kelsher was marked across of the corner with 1988 was 4 feet	stablishing corr sey Highway scording to was establis	ner: was ree the pla shed us:	establi ans. I ing the	shed he ar high	by ea wa	
		· ·								•
C. [Description of monun	nent for corner and ac	cessories est	tablished to perpetuate	locating the po	sition of th	e corner:			
3et Monu	a 30" long fibe ment - Do Not 1	arglass monument Disturb"	t with a 4	" diameter bronz	se cap stamp	ped "Io:	nia Cou	nty S	urvey	7 3
Vail Vail Vail	and tag South and tag North	side 6" wood po West side power side 14" Elm st side 24" Hickory	r pole S tump N 88°	32° E 56.20' 'E 36.53'						
		_/		2.12						
Signe	ed by	rary a	STUR	202 Date_	Novembe	er 1, 19	93		· · · · · · · · · · · · · · · · · · ·	
-Surve		nse No. <u>25863</u>	<u> </u>	· · · · · · · · · · · · · · · · · · ·	FORM APPROVED BY	' MICHIGAN STAT	E BOARD OF LAI	REV	ORS, JAN, 2 ISED MAY 1 EVISED JAN	14, 1975