1095

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in IONIA (County)	Located In:	Corner Code #	LIBER	003	PAGE 19	4		
1. Public Land Survey	T7N R8W T R R R R R R R R R R R R R R R R R R	<u>E-10</u>	STATE OF MICHIGAN IONIA COUNTY RECEIVED FOR RECORD					
2. Property Controlling Sin Section S	T R T R T R		10 OCT 95 4:04 P.M. Register of Deeds Stamp & File Number DIANE M. AUAMS REGISTER OF DEEDS					
4. Lot No, Recorde 5. Private Claims	d Plat		1 <u>A</u>	B C D	E F G	; H I	JK	L
5, Private Clarits		, , , , , , , , , , , , , , , , , , ,	2 3	6 5	4	3	2	
I, MARINUS MULDER in a field survey on JUNE 13 19 9 5, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in				7 8	ġ	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. or 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:			of Land 6	18 17	16	15	-14	- 13
			cree of a	19 20	21	22	23	24
			10	30 29	28	27	26	- 25
			11	31 32	33	34	3 5	36
WAS SET WITNESSED BY A PERPETUATION: THERE AR COMMISSION RECOVERED WAS FOUND AND WITNESS 20" OAK S 25° E 89.10 FEE 18" ELM S 53° W 48.3 FEE	C 10" WHITE OAK NEE NO RECORDED C AND WITNESSED T SED TO THE FOLLO T	J.S. DEPUTY SURVEY NOAH IN 80° W 38 LINKS AND A 12 COUNTY SURVEYS FOR THIS THIS CORNER WHILE UPGRAD OWING OBJECTS:	" WHITE OA CORNER. T DING MARB	AK S 26° THE ION	W 23 LI IA COUN	NKS. ITY RO	DAD	`
FOUND, 1/2" ROD OVER 1/2 A LARGE STONE 26" DEEP	" ROD AND CAP S AND 4 FEET MORE OAD. FOUND NO	ethod applied in restoring or reesta ET BY MEDEMA & VAN KOU OR LESS SOUTH OF THE CE OTHER EVIDENCE AROUND C	TEN NO. 86 ENTERLINE C	18. BEL OF SAYL	ES ROAL	ONA C	ON	JND THE
ı	•							
· ·								
SET 3/4" X 24" STEEL ROD	for corner and access WITH A 2 3/4" DI/	cories established to perpetuate lo	ocating the po HE 1/2" ROI	sition of t	the corner	: HE ST	ONE,	-
WITNESSED BY: NAIL & TAG EAST SIDE 5" I NAIL & TAG WEST SIDE 12' NAIL & TAG NORTHEAST SI CENTERLINE ROAD SIGN (2'	" ELM S 28° W 32. IDE 18" WALNUT 5	05 FEET 3 34° E 50.10 FEET	P.A. Date	345 fc	Poor G min Cot 7 - 95 ulder, Ch	inty		
Signed by marin (a. mill	2 Date	October	r 2, 199	5			
Signed by 770000000000000000000000000000000000								