## FEB 1-8 1994

## REMONUMENTATION

COMMISSION

Surveyor's Michigan License No. \_\_\_\_25863

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  Ionia	Located In:	Corner Code ##	93 25 5
· (County)			STATE UF IONIA CONTROLLE STATE UT IONIA CONTROLLE STATE UF IONIA CONTRO
Public Land Survey	T <u>7N</u> R _7W T R	B11	TERO
	T R		7√0 295
Property Controlling S	T R ; T R		P1:0
in Section S	s T R		38. W. N.
	s		Register of Deeds Stamp & File Number
Property in Sec. S	i R		
4. Lot No, Reco	rded Plat	100	A B C D E F G H I J K L M
5. Private Claims		- Laboratory - Marketon - Laboratory - All Street	2 6 5 4 3 2
			3
i			4 7 8 9 10 11 12 12
Marinus Mulder . in	a field survey on _Septer	nber 15 , 19 93 ,	5
in lines 1 and 2 above were in con	nformance with regulations ar	of 1970, the corner points mentioned rules therefore as required in the	
current manual of survey instruction	ns of the United States Depar	tment of the Interior, Bureau of Land er points mentioned in lines 3, 4 and 5	·
above were in conformance with the	e rules of the Michigan Board o	of Land Surveyors or by a Decree of a	
Court of Law; established, re-est	tablished, monumented, re-	monumented, recovered, found as	10 30 29 28 27 26 25
expressed below:	and all in the same town a	nd range may be recorded	11
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12 31 32 33 34 35 36
			13
A. Description of original month	ument and accessories and	d/or subsequent restoration:	don A wood nost was sot :
witnessed by a 12" El	lm S 47° W 31 links	and a 8" Beech N 67°	don A wood post was set E 36 links. This was set in 1831.
PERPETUATION: D.C.	Crawford former Ion	nia County Surveyor per	formed a survey in the NW 1/4
records. Crawford ma	akes no mention of	B-11, but shows that h	page 402 of the County Surveyors e did set the section center.
Richard Crater, Profe Liber 2 page 263. Cra	essionalSurveyor #1 ater called for a (	16924 recorded this cor corner post at the inte	ner October 23, 1986 found in ersection of fences.
Tom Chettleburgh, Pro (see back)  B Description of corner evider	ofessional Surveyor	c #16036 also did some applied in restoring or reestablish	work in this section and a 3/4" hing corner:
We made a thorough sea	arch of the area ar	nd also had field measu	rements to adjacent section Accepted the position of
Chettleburgh's iron a	and replaced this w	with a 3/4" x 36" steel	rod.
	•		
		established to perpetuate locatin	
Set a 3/4" x 36" stee by:	el rod with a 2 3/4	" cap stamped "Ionia C	ounty P.S. 25863" Witnessed
Nail & tag South side	a 12" Marala North 5	, EU;	
Nail & tag North side	8" Maple N 55° E	18.22'	
Nail & tag West side			
Nail & tag North side	2 12" Ash East 37.1	8'	
	·		<i>,</i>
	<i>j</i>	2	
Signed by	a milde	Date	10–19–93

## B. con't.

 ${
m rod}$  and cap bearing his number was found at the position of B-11 which matched the witness distances of Crater.