Curvey & REMONUMENTATION

DEC 1 6 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

LIBER J PAGE 246

 ?	÷ 1		F	iling Requirement of	Act 74, Mich. P.A. 1970							•
For corners in 10N1A (County)		Located	In:	Corner Code #				I	ONIA CI	ICHIGAN DUNTY DR RECO		
Public Land Survey			_R7W				·	24 00	F 96 :	3:51 P.	Ħ.	
		T	_ R							adans of Deed	18	
Property Controlling in Section Miscellaneous Property in Sec.	S S S	T T	R R R			Registo	er of D	eeds S	Stamp	& File I	Numbe	er
4. Lot No, Re 5. Private Claims	corded Plat _		<u></u>			.1	A B	C, D	ЕF	е н	IJĸ	LN
						2	6	5	4	3	2	1
				ey on JULY 8		4	7	8	9	10	11	12
lines 1 and 2 above wo current manual of surve	rere in conf y instruction	formance is	with regu Inited Sta	lations and rules t tes Department of	the corner points mentioned herefore as required in the linterior, Bureau of Lan	ne δ	18	17	16	15	14	13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				a 。	19	20	21	22	23	24		
		in the same	town and	range, may be recorde	d .	10 11	30	29	28	27	26	25
A. Description of original m	· · ·	accessories a	and/or subse	quent restoration:		12 13	31	32 .	33	34	35	36
					SDON IN 1831. A WOOD POS			TNESSE	D BY A	8" BEE(CH S 36	° E 7

THE IONIA COUNTY ROAD COMMISSION IMPROVED AND PAVED JOHNSON ROAD IN 1963. THIS INFORMATION IS FOUND ON SHEET 3 OF PROJECT 34-76. THE COUNTY WITNESSES SHOW A BOAT SPIKE WAS SET WITNESSED BY A: 12" WALNUT S.W. 32.64'; 12" WALNUT S.W. 36.60'; 18" WALNUT N.W. 49.04'. THE PLANS DO NOT SAY WHAT EVIDENCE WAS FOUND IF ANY. THE PLANS DO SHOW FENCES GOING EAST AND WEST FROM THIS LOCATION.

PROFESSIONAL SURVEYOR JAMES PORTER NO. 19003 RECORDED C-9 OCTOBER 8, 1980, FOUND IN LIBER 2, PAGE 99. PORTER SAID A POINTED 1/4" ROD WAS FOUND WITNESSED BY: NE CORNER WORKSHOP NW 100.50'; SE CORNER WORKSHOP NW 79.48'; P.K. NAIL 30" WALNUT WNW 63.95'; P.K. NAIL 30" WALNUT NW 48.64'.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4"X8" BOAT SPIKE 5" BELOW THE PAVED SURFACE OF JOHNSON ROAD. THERE IS A 8"X8"ANCHOR POST AND FENCE LINE TO THE WEST OF THE BOAT SPIKE, BUT NO OCCUPATION LINE TO THE EAST. EXCAVATED TO A DEPTH OF 36" BELOW ROAD SURFACE BUT FOUND NO OTHER EVIDENCE. ACCEPTED THE POSITION OF THE BOAT SPIKE AS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER.

Description of monument for corner and accessories established to perpetuate locating the position of the corner; SET A-30" ALUMINUM MONUMENT WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY 25863" IN PLACE OF BOAT SPIKE. WITNESSED BY:

NAIL & TAG SOUTH SIDE GUARD RAIL FOST S 71° W 18.53' NAIL & TAG SOUTH SIDE GUARD RAIL POST N 40° W 24.19' NAIL & TAG TOP GUARD RAIL POST N 80° E 17.53' NAIL & TAG TOP GUARD RAIL POST S 25° E 79.42' SOUTHEAST CORNER BLOCK GARAGE N 25° W 79.42' SOUTHWEST CORNER BLOCK GARAGE N 38° W 93.49'

25863

Surveyor's Michigan License No.



Ratified by Peer Group P.A. 345 Ionia County

Date . 9-36-96 Marinus A. Mulder, Chairman

gned by Mail a Mulch Dain OCTOBER 22, 1996	ined by Mak	la mulla	Date OCTOBER 22, 1996	
--------------------------------------------	-------------	----------	-----------------------	--

REVISCO MAY 16. 1976