DEC 1 8 1996

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 IBER 3 PAGE 254

1			•	•	\
For corners in					* *
ION1A (County)	Located in:		Corner Code #	STATE OF MICHIGAN IONIA COUNTY RECEIVED FOR RECORD	
<ol> <li>Public Land Survey</li> </ol>		T 7N⊬ R 7W√		J-6	J-6
		T R			24 OCT 96 3:53 P.M.
•		TR_			DIANE M. ADAMS
2. Property Controlling	S	T R_	Γ R		REGISTER OF DEEDS
n Section	S	T R_			_
3. Miscellaneous	S	T R			Register of Deeds Stamp & File Number
Property in Sec.	s	T R_		A look of the right of the righ	
4. Lot No.	Bacord	ed Plat			, A B C D F F G H I J K I
					, , , , , , , , , , , , , , , , , , , ,

in a field survey on February 6 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

2 3 4 7 Я 10 11 12 5 ó 18 17 16 15 164 13 7 19 8 20 21 22 23 24 10 30 29 28 25 26 11 12

The center of Section was not set by U.S. Government Surveyors. There is no written record of establishment by Ionia County Surveyors. Establishment - Professional Surveyor, Pete Beaver No. 25828 set J-6 in October of 1988 by intersecting the North-South and East-West 1/4 lines. This is recorded in Liber 2, page 337 of Ionia County records. Pete set a 3/4" pipe and cap and established 4 witnesses:

Nail & tag East side 20" White Oak N 10° W 36.57 feet

Nail & tag South side 6" White Oak S 80° E 8.05 feet

Nail & tag North side 15" Hickory S 70° W 6.78 feet

Nail & tag North side 24" White Oak N 70° W 13.57 feet

Description of corner evidence found and/or method applied in restoring or reestablishing corner; Beaver's corner is located 26 feet East of a North-South fence line & within an existing East-West fence line. Intersected the North-South and East-West 1/4 line and agreed with the position of Beaver's corner. Removed 3/4" pipe and set a 3/4" x 36" steel bar with cap.

Description of monument for corner and accessories established to perpetuate locating the position of the corner; Set a 3/4" diameter x 36" steel rod with a 2 3/4" diameter cap stamped "Ionia County P.S. 25863" witnessed by: Ratified by Peer Group

Nail & tag East side 28" Oak N 45° W 16.88 feet

Nail & tag North side 18" Hickory N 74° W 5.27 feet

Nail & tag South side 8" Oak N 02° E 8.00 feet

Surveyor's Michigan License No.

Nail & tag Boutheast side 18" Oak S 48° W 36.98 foot

P.A. 345 Ionia County

TOPO LAND

MULDER LAND SURVEYOR No. 25863

9-26-96 Date

Marinus A. Mulder, Chairman

Signed by\_ OCTOBER 22, Date

form approved by Mighigan State Board of Land Surveyors, Jan. 78, 1971