SURVEY & REMONUMENTATION

JAN 2 0 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION For corners in	Filing Requirement of Act 74, Mich. P.A. 1970 LISER 4 PAGE 40								
IONIA (County)	Located In:	Corner Code #					TCHTGA:	Ŋ	
1. Public Land Survey	T8_N R5_W C-8 T R				RETE		ur mic		
Property Controlling in Section S Miscellaneous	T R R R R R R R R R R R R R R R R R R R		Registe	er of D	\mathbb{R}]	IANE HI.	2:51 P ADAHS File N	į	r
Property in Sec. S	TR				C D				· · · · · · · · · · · · · · · · · · ·
5. Private Claims			2	6	5	4	3	2	1
I, MARINUS MULDER , in a field survey on AUGUST 11, 1998 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Landangement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and			4	7	8	9	10	11	12
			the and 6	18	17	16	15	14	13
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law; established, re-established, monumented, re-monumented, recovered, found a expressed below:			ofa _	19	20	21	22	23	24

PERPETUATION: D.C. CRAWFORD FORMER IONIA COUNTY SURVEYOR PERFORMED A SURVEY OF SECTION 19 APRIL 26, 1890, RECORDED IN

D.C. CRAWFORD ALSO PERFORMED A SURVEY OF SECTION 20, APRIL 29, 1890 RECORDED IN VOLUME 2, PAGE 140 OF THE IONIA COUNTY SURVEYORS RECORDS. CRAWFORD DID NOT STATE WHAT WAS FOUND OR SET FOR C-8.

VOLUME 2 PAGE 130 OF THE IONIA COUNTY SURVEYORS RECORDS. CRAWFORD DID NOT STATE WHAT WAS FOUND OR SET FOR C-8.

THE IONIA COUNTY ROAD COMMISSION IMPROVED HAYES ROAD IN 1950. PROJECT CS-34-58, ON SHEET NO. 5 OF THE ROAD PLANS, THE WITNESSES FOR C-8 ARE: 1" CHROME ROD OVER A LARGE STONE- N.W. CORNER OF BARN N 64° E 110.90 FEET; S.W. CORNER BARN S 83° E 99.60 FEET; 3" ELM S 83° W 45 FEET; CORNER FENCE POST N 88° W 33.48 FEET; 20" HICKORY N.N.W. 92.60 FEET.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: THE OLD BARN USED AS A WITNESS BY THE ROAD COMMISSION STILL STANDS. MEASURED THE WITNESS DISTANCES AND EXCAVATED THE ROAD BED. AT A DEPTH OF 3" FOUND A RAILROAD SPIKE. AT A DEPTH OF 12" BELOW THE SURFACE FOUND A 1" STEEL SHAFT 15" LONG NEXT TO A LARGE STONE. NO OTHER EVIDENCE WAS FOUND.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: REPLACED EXISTING MONUMENTATION WITH A 7/8" x 24" SOLID STEEL BAR WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY-P.S. 25863" WITNESSED BY:

NAIL & TAG **NAIL & TAG**

MOTE:

on this certificate.

NORTH SIDE 24" TWIN OAK **NORTHWEST SIDE 28" WALNUT**

Not more than 4 corners, all in the same town and range, may be recorded

THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR ORANGE RISDON IN 1831. A

WOOD POST WAS SET WITNESSED BY A 18" WHITE OAK N 29° W 4 LINKS, AND A 9" HICKORY S 29° E 4 LINKS.

A. Description of original monument and accessories and/or subsequent restoration:

NORTHWEST CORNER BARN SOUTHWEST CORNER BARN

WEST 34.05 FEET S 37° W 60.16 FEET

> N 66° E 110.71 FEET S 84° E 99.60 FEET

Ratified by Peer Group P.A. 345 Ionia County

Date 9-16-98

20

32

10 30

11

12 31 28

33

27

34

Marinus A. Mulder, Chairman

MARINUS A MULDER LAND SURVEYOR NO. 25863 Marian 2 a Mulde Signed by_

Date

11-11- 98

25

36

26

35