LAND CORNER RECORDATION CERTIFICATE

4.00

Filing Requirement of Act 74, Mich. P.A. 1970

	•	•	LIBE	RVVJ	PAGE 🛶	47				
For corners in IONIA	Located In:	Corner Code #	I							
(County)	Located in.	Comer Code #		ē.	TATE OF M	TPUTGAN				
				ā	IONIA C					
4 8 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	70 N DF 14/	0.40		RI	CEIVED F		en			
Public Land Survey	18 N H5 VV	T8 N R5 W G-12				KEBELVED FOR MEGOND				
	'	TR					16 NOV 95 4:23 P.M.			
	TR	**************************************								
2. Property Controlling	STR				DIANE M.	adams				
in Section	STR		Registe	r of Deed	EGISTER (E PER	diimhe	»F		
3. Miscellaneous	S T R		registe	or Beec	is ownp	<u> </u>	10	•		
Property in Sec.	S T R									
4. Lot No. , F	Recorded Plat			N D C	D F F	с и і	. 1 12			
5. Private Claims			1′	1 B C	D E F	<u>Б н і</u>	JK	LN		
			2	6	5 4	3	2	1		
			3			ļ				
i, MARINUS MULDI	ER , in a field survey	on AUGUST 23, 19 95,	4	7 7	8 9	10	- 11	12		
I, <u>MARINUS MULDER</u> , in a field survey on AUGUST 23, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						-				
	in conformance with regulations a structions of the United States Dep			18 1	7 16	15	14	13		
Management or by a decree	of a Court of Law and/or that the co	rner points mentioned in line	s 3, 4 and 5 7					<u> </u>		
	with the rules of the Michigan Board, re-established, monumented,			19 2	20 21	22	23	24		
expressed below:	u, re-established, monumented,	re-monamented, recovered	9							
·			10	30 2	9 28	27	26	25		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			d 11							
on this certificat	e.		12	31 3	2 33	34	35	36		
A. Description of origin	nal monument and accessories a	nd/or subsequent restora	tion: 13							
	RST ESTABLISHED BY U.S.									
	BY A 40" WHITE OAK S 49					THEF	RE IS	NO		
RECORDED DOCUMEN	ITATION OF THIS CORNER E	EING PERPETUATED I	BY THE COUN	TY SUR	/EYOR.					
B. Description of corne	er evidence found and/or method	applied in restoring or re	establishing cor	ner:						
	LINES EXCAVATED AROUND				GE PILE	OF ST	ONES			
	RTH FROM THIS POINT BUT									
	AN ANCIENT FENCE. THEF									
	N EAST-WEST DIRECTION.									
	E MEASURED DISTANCE TO									
THE STONE PILE AS T	HE BEST AVAILABLE EVIDEN	ICE AS THE POSITION	l OF G-12.							
							•			
	,							•		
C. Description of monu	ment for corner and accessories	established to perpetuat	e locating the po	sition of	the corne	r:				
	EL ROD WITH A 2 3/4" DIAM						ESSED)		
BY:										
NAIL & TAG NORTHW	EST SIDE 12" CHERRY N 58	° E 22.30 FEET						•		
	E 4" CHERRY N 7° E 11.89 F		.							
	OOT OF 36" OAK STUMP S		Ratified by							
NAIL & TAG NORTH S	IDE 6" OAK S 75° E 15.80 F	EET	P.A. 345 I	onia Co	ounty					
			Date 4/17	1.1.19	795					
			Marinus A. N	Aulder B	halman					
			mannus M. N	idiusi, G	наннац					
Signed by Mari	il a mulla	- Date	11-14-	95						
0.900 27			······································							
Surveyor's Michigan Licer	nse No. <u>25863</u>		FORM APPROVED BY	MICHIGAN STA	TE BOARD OF L	REV	ORS, JAN. ISED MAY ISVISED 14	14, 1975		

REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993