SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

		ring Ke	equireme	ent of Act	74, Nuch. I	F.A. 1970				<i></i>	. 44	5	元 円 い	
For corners in	,			Corner Cod	o #	ſ			(B)	\lesssim		-	GaZ.	
IONIA (County)	^L	ocated In:		Corner Cod	е #				हाडीडा इ.स.	5	A CAR	Ē	公室門 四方位	
						Ì			ŭ	3	77		2013 2013	
Public Land Survey	7	r8NR6W		T - 2		}			<u>;</u>	3			SEE SEE	
1. Fublic Latte Survey		Γ <u> </u>							51.00		u L	り ン		
		Γ R							ć	7 (4	ک	1758 1758 1758 1758 1758 1758 1758 1758	
		r R								1,	(ىن		
2. Property Controlling		Г R												
in Section		r R				Regi	ster	of De	eds St	amp &	File N	umber		
3. Miscellaneous	S7	[R	-			<u> </u>					,			
Property in Sec.	S1	FR	-											
4. Lot No, F	Recorded P	'lat		•						. - /				
5. Private Claims							1 A	В (, υ.	<u> </u>	∋ H I	l l X	L M	
•							2	6	5	4	3	2	1	
							3 -							
I, MARINUS MULDER		, in a field s	survey on	JUNE 21,	1994 ,		4	7	8	9	10	11	12	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points														
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the								18	17	16	15	14	13	
Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points							7							
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,							8	19	20	21	22	23	24	
re-monumented, recovered				,	· , · ·		9 -	20		00	0.7	24	25	
NOTE: Not more than A	antone a	il in the same to	own and	rango may	ha racardad		10	30	29	28	27	26	25	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.							12	31	32	33	34	35	36	
							13	<u> </u>	0 <u>7</u>			- 00		
A. Description of origin	nal monum	ent and accesso	ories and	or subseque	ent restorati	on:								
THIS CORNER WAS FIRST 18" WHITE ASH N 51° E THERE IS NO RECORD OF THE IONIA COUNTY ROAD NO. 11 OF STATE PROJEC 30" ELM SOUTH-SOUTHEAS 24" MAPLE S.W. 31.45' CORNER FENCE POST NORT CORNER FENCE POST SOUT	47 LINKS ANY COUNT COMMISSIO T CS 34-8 T 30.20 TH-NORTHWE	AND A 16" WHIT Y SURVEYS IN S IN RECONSTRUCTS	TE OAK S SECTION : ED AND P	51° W 20 L 2 OR 3.	INKS. LECK ROAD I	IN 1962. I	PLAN	INFO						
B. Description of corne	er evidence	found and/or n	method ap	oplied in rest	oring or ree	stablishing	corn	er:						
EXCAVATED ROAD AND 2" BELOW SURFACE FOUND 1/2" ROD. REMOVED ROD AND AT A DEPTH OF 16" FOUND A 3/4" X 8" BOAT SPIKE. BELOW BOAT SPIKE AT A DEPTH OF 24" FOUND A LARGE POINTED STONE. ACCEPTED THE POSITION OF THE BOAT SPIKE AND STONE AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.														
							O	afifi	ے اس		_			
								Ratified by Peer Group P.A. 345 Ionia County						
							and of to total country							
								Date /A 2 - C						
							Date /D-20-94 Marinus A. Mulder, Chairman							
							1417	nmas	A. W	ulaer,	Chairr	nan		
C. Description of mon	ument for	corner and acce	ssories e	stablished to	perpetuate	locating th	е ро	sition	of the	corne	r:			
REMOVED THE 1/2" ROD A	NT DONT C	OTER AND SET (a 24" FT	REPOLASS MO	ייי אייי איייי	"H A 4" DT	AMET	ER BR	ONZE (CAP ST	AMPED	"IONI	A	
COUNTY SURVEY MONUMENT NAIL & TAG NORTH SIDE NAIL & TAG EAST SIDE & NAIL & TAG WEST SIDE & NAIL & TAG WEST SIDE &	- DO NOT 6" CHERRY 3" WOOD PO 5" WOOD PO	DISTURB" WITH CLUMP S 58° E ST NORTH 34.7 ST N 18° W 36.	NESSED B E 75.35' ' .39'											
_	1.	000 01	1			11	/	_ 0	4					
Signed by Mari	y a	"Musel	<u> </u>		Date	(/ -	_/	-9	7					
Surveyor's Michigan Lice	nse No	25863		<u>.</u>		FORM APPRO	VED BY	MICHIGA	n state b	OARD OF L	RE		Y 14, 1975	
									ADAPT	ED FOR W	ORD PROCE			