

FEB 1 6 1999

REMONUMENTATION CORNER

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

SECTION -		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970				STATE OF MICHIGAN IOSCO COUNTY								
For corners in							FI	LED						
(OSCO (County)	Located In:	Corner Code #				8 DEC	98	1:1:	5 P.i	1.				
1. Public Land Survey	T <u>21NR 6E</u> T <u>R</u> T_R_ T R							H. C(OF)		î				
2. Property Controlling in Section S_ 3. Miscellaneous S_ Property in Sec. S_	T R T R T R													
, -				Regis	ster	of De	eeds	Stan	ıp &	File N	lumbe			
4. Lot No, Recorded 5. Private Claims	Plat		A 1 ;	В	Ċ	D E	F	G	Н	ı j	K L			
			2	6	1	5	d		3	2	ı			
			3		;	;					•			
1 JAMES H. GRANGER in a	field survey on SEPTEN	/IBER 29 19 98 do hereby state that	4	: 7		ο.	Q		10	1.1	12			
I, <u>JAMES H. GRANGER</u> , in a field survey on <u>SEPTEMBER 29</u> , 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above			5	:	:		,		10	1.3.	12.			
were in conformance with regulations instructions of the United States Depart	and rules therefore as re Iment of the Interior, Burea	equired in the current manual of survey u of Land Management or by a decree of	5 ;		:	1		,						
a Court of Law and /or that the corner p	ooints mentioned in lines 3,	4 and 5 above were in conformance with	7 !	18		1 7	16		15	14	13			
the rules of the Michigan Board of t re-established, monumented, recovered		Decree of a Court of Law; established, w:		1.0		20	0.1		0.0	0.0				
			8 ;	19		20	21		22	23	34			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9 ;	:		; .								
on this certificate.	3		10	30	-	29 -	28		27	26	25			
			11	:	;	i								
A. Description of original monume	ent and accessories and	d/or subsequent restoration:	12	31	:	32	33		34	35	36			
No original GLO corner set			13											
			OF 345	FICIA FICIA	Y P NL C 199	HEEN AROK TA 0	ER U A ME	JNDE JNDE	ISTI ERF NG	OUN HE .A	ľΥ			
			HE	LD O		9-								
B. Description of corner evidence	e found and/or method a	applied in restoring or reestablishing	comer:		fa	emb	r EF	Mi	ar	ega				
Establish corner location midw	ay and online between l	NE cor. Sec. 1 and NW corners of Se	c. 2											
	•													
		•												
C. Description of monument for co	orner and accessories e	stablished to perpetuate locating the	positio	n of t	he	corne	r:							
Set 5/8" x 24" Iron rod w/remon	сар			الإجعب		(45)	i.							
W Birch 12" dia. Aspen 8" dia	N23°E 16.77' S44°F 20.49'	nail & tag		TE	OF معمر	M/C	YICA							



Signed by <u>fames & Stranfer</u> Surveyor's Michigan License No. 16041 Date __ November 2, 1998

NE cor. garage

nail & tag

S30°W 60.96'

S71°W 58.16'

NE cor. Block foundation

Twin Maple 12" dia.