For corners in	LAND CO	O COUNTY REMONUMENTATION RNER RECORDATION CERTIFIC quirement of Act 74, Mich. P.A. 1	ATE			1	<b>3</b> )	ζ	j) =	şîn)		ري کا	<u>)</u> )	<u> </u>	
losco	Located In:	Corner Code #							STA	iTE C	JF H	TCH:	LGAL	Į	
(County)		<u> </u>								1050			ΪĬ		
I. Public Land Survey	T <u>21NR 6E</u> T 21NR 7E	M-8 VX 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1									FIL	ΕĐ			
	TR							2	0 1	EC 9	19 1	0 1	3 A.	M.	
2. Property Controlling in Section 3. Miscellaneous	TR S TR S TR S TR									ONIT GIST					
Property in Sec.	S TR		ı	₹egi:	ster	of	Dec	eds	Sta	mp	<b>&amp; F</b> i	ile N	lum	ber	
1. Lot No, Rec	orded Plat		A	В	c	D	F	F	G	11	т	.1	k	1. 1	14
			1												٠
o. Private Claims	<u></u>	1 to	3	6		5	:	4		3		2		1	
			4	7		8		9		10		11		12	
IAMES II CRANCER	in a field	survey on November 19.99 do	5												
JAMES H. GRANGER , in a field survey on November , 19 99 do nereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as						17		16		15		14		13	
equired in the current man	ual of survey instructions of	the United States Department of the	7 8	19		20		2.1		22		23		-5.4	_
nterior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,						20		21		22		2.)		24	•
						20		28		27		26		25	
nonumented, recovered, found	as expressed below:		10 11	30		2.9				_,		2.0			
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.						32		33		34		35		36	
				٠											
A. Description of original n	nonument and accessories a	and/or subsequent restoration:													
1837 GLO	Set Wood Post	S32"W 17lks													

6" Cedar

N28 'W 36lks

1998 Survey

Set corner & 4 witnesses

James H. Granger 16041

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1998 comer marker. Found 1914 survey documents on Mc Mullen Drain showing corner to be on W. side of Drain. 1998 corner on E. side of Drain. No original evidence found at either location due to Drain constr. With no other documentation available and considering parol evidence of long time property owners, it was concluded that corner position is on W. side of Drain. Measured S. from NE cor. using data from 1914 Drain survey to establish corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" x 30" rebar w/ Remon Cap Post N65 E


4" Cedar Post S5 W 14" B. Ash

S65 E N72 F

22.55' nail & tag 16041 34.78' nail & cap 16041 65.57' nail & cap 16041 93.19' nail & cap 16041

14" Dbl. B. Ash at east edge of Mc Mullen Drain ACCEPTED BY THE IOSCO COUNTY SURVEY PEER GHOUP AS THE CFFICIAL CORNER UNDER P.A. 345 OF 1890 AT A MEETING HELD ON 10-13-99

James H. Langer



Signed by James 4

December 15, 1999 Date

Surveyor's Michigan License No.

/ED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

258

4PR 07 2000

SECTION

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995