IOSCO COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

9	9)	ন্দ্ৰে।
---	----	---------



STATE OF MICHIGAN

losco (County)	_ Located In:	Comer Code #				IOSCO COUNTY FILED										
1. Public Land Survey	T 21NR 6E M-9 35 T 21NR 7E A-9 (15)	A-9 (Qhaday (C)	ha to see to				20 DEC 99 10:13 A.M.									
Property Controlling in Section Miscellaneous Property in Sec.	TR TR STR STR STR STR		I	Regi	iste	r of∣	Dec	KE	615	TA H TER mp &	UF	DES	1 59	ber		
4. Lot No, Reco	rded Plat		, A 1 :	В	С	D	E	F	G	Ħ	I	J	K	L	ì	
5. Private Claims			6		5	:	4		3		2		1			
			3		i		:	9		10		11		12		
			5				:	,		10		11		12		
I, <u>JAMES H. GRANGER</u> , in a field survey on <u>November</u> , 19.99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,			6	18		17		16		15		14		13		
			7													
			8	19		20		21		22		23		24		
			9												•	
monumented, recovered, found a	as expressed below:		10	30		29		28		27		26		2,5		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded		11 12	31		32		33		34		35		36			
on this certificate.			13			;	:			~ .						

A. Description of original monument and accessories and/or subsequent restoration:

1837 GLO

For corners in

Set Wood Post

Lewis Clawson

16"Spruce

S85°W 8lks

7" Cedar

N59"W 16lks

1998 Survey

Set corner & 4 witnesses

James H. Granger 16041

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1998 corner marker. Found 1914 survey documents on Mc Mullen Drain showing corner to be on W. side of Drain. 1998 corner on E. side of Drain. No original evidence found at either location due to Drain constr. With no other documentation available and considering parol evidence of long time properly owners, it was concluded that corner position is on W. side of Drain. Measured S. from E1/4 cor. using data from 1914 Drain survey to establish corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" x 30" rebar w/ Remon Cap Cedar Post N59 W

6" Ash N35" E 5" Ash S38" W 4" Dbl. Ash S83" W 14.05' nail & tag 16041 55.08' nail & cap 16041 65.25' nail & cap 16041 54.68' nail & cap 16041 ACCEPTED BY THE IOSCO COUNTY SURVEY PEER CHOUP AS THE CHICAR CHICAR PLASS OF 1900 AT A MEETING HELD ON 10-13-95



Date December 15, 1999

Signed by James H. Manger
Surveyor's Michigan License No. 16041

SUBVEY A REN

APR 2 7 2000

SECTION

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995