

**FEB 15 2001**

**SECTION**

**IOSCO COUNTY REMONUMENTATION CORNER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

**074 2001**

For corners in

IOSCO (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>22N</u> R <u>5E</u>	M - 10 ✓
	T <u>22N</u> R <u>6E</u>	A - 10
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

STATE OF MICHIGAN  
IOSCO COUNTY  
FILED

13 FEB 2001 9:21:24 AM

BONITA H. COYLE  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, **William J. Rigg, P.S.**, in a field survey on **October 12 2000** do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:  
1844 +/-, GLO Survey, set post, 8" W. Pine, S56W 12 lks, 12" W. Pine, N39W 12 lks  
1986 Timothy L. Lapham, Found 1" pipe at fence to West, See LCRC 86 - 04

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


Found and accepted 1" pipe as evidenced, witnesses check.

ACCEPTED BY THE IOSCO COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON 10-11-2000

*James H. Stranger*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1" pipe with 5/8" rerod and Remon Cap  
S45W - 8" Maple - 22.54'  
N45W - 18" Maple - 39.75'  
N50E - 16" Twin Maple - 33.40'  
West 0.5 ft. - Fence Post



Signed by *William J. Rigg P.S.*  
Surveyor's Michigan License No. #41108

Date December 22, 2000