

FEB 2 1996

IOSCO COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

95-22

For corners in

IOSCO (County)	Located In:	Corner Code #
1. Public Land Survey	T22N R8E	1-5
	T___ R___	_____
	T___ R___	_____
	T___ R___	_____
2. Property Controlling in Section	S___ T___ R___	_____
	S___ T___ R___	_____
3. Miscellaneous Property In Sec.	S___ T___ R___	_____
	S___ T___ R___	_____

STATE OF MICHIGAN  
IOSCO COUNTY  
FILED

12 DEC 95 2:23 P.M.

BONITA M. COYLE  
REGISTER OF DEEDS

Registrar of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

James H. Granger, in a field survey on November 7, 1995 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1837 Original Survey Wood Post  
8" Spruce Pine S41°W 12 lks.  
6" Spruce Pine N20°E 25 lks.
- 1976 Private Survey found conc. monument
- 1992 Private Survey 1/2" rebar with cap #16041 at conc. mon.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rebar previously established


ACCEPTED BY THE IOSCO COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 10-31-95

*James H. Granger*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 5/8" x 30" Rebar with aluminium cap
- 12" Jack Pine West 49.51' set nail and tag
- 6" Oak S15°E 106.15' set nail and tag
- 10" Jack Pine S70°E 68.75' set nail and tag
- 4" Jack Pine N25°E 23.30' set nail and tag

E. Face Steel I beam gate post S50°W 36.10



Signed by James H. Granger  
Surveyor's Michigan License No. 16041

Date December 6, 1995