LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N., R. 9 E.	C-6; B-6;
2. PROPERTY CONTROLLING IN SECTION 18,	T. 24 N., R. 9 E.	5; 9
3. MISCELLANEOUS PROPERTY IN SECTION ____,	T. ____ N. S., R. ____ E. W.	
4. LOT NO. ____, RECORDED PLAT ____		
5. PRIVATE CLAIMS ____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, KENNETH J. OSTLING, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on SEPTEMBER 14, 19 83, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

B-6

DNR MONUMENT 4" CASING FILLED WITH CONC W/CAP
6" RED PINE S76°W 46.9'
10" RED OAK N22°E 62.6'
POST WITH LOCATION TAG 20' WEST

9

SET 5/8" IRON BAR
6" OAK S70°W 13.63'
7" OAK N17°W 11.73'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-6 - FOUND 1" PINCHED PIPE, ORIGIN UNKNOWN, BUT ONLY THING AVAILABLE FOR CORNER. NE CORNER IN LAKE AND SE CORNER IN AIRBASE, MAKING CONFIRMATION DIFFICULT.
5 - SET BY STANDARD SURVEY PROCEDURE FOR THE SUBDIVISION OF SECTIONS.
B-6 - FOUND MONUMENT LYING DOWN, APPARENTLY DISTURBED IN ROAD CONSTRUCTION. RESET UPRIGHT, AT LOCATION DESCRIBED IN PREVIOUS OBSERVATION.
9 - SET BY STANDARD SURVEY PROCEDURE FOR THE SUBDIVISION OF SECTIONS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6

LEFT 1" IRON PIPE IN PLACE
16" R. PINE S40°W 7.8'
6" R. PINE N89°E 43.0'

5

SET 5/8" ROD W/RLS CAP
8" J. PINE N41°W 26.8'
12" J. PINE S84°E 20.5'
FOUND 5/8" ROD N88°E 17.4'

SIGNED BY Kenneth J Ostling DATE 2/6/86

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ DATE ____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ____ DATE ____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN (SEAL) KENNETH J. OSTLING LAND SURVEYOR No. 10068 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. ____ IOSCO COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET