## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

CORNERS OF -: LOCATED IN -:  1. PUBLIC LAND SURVEY T. 41 N. R. 32 V.  2. PROPERTY CONTROLL-11 T. 41 N. R. 32 V.  3. MISCELLANEOUS PROPERTY IN SECTION T. N. R. S. R. V.  4. LOT NO. RECORDED PLAT  5. PRIVATE CLAIMS RECORDED PLAT  6. PRIVATE CLAIMS RECORDED PLAT  6. PRIVATE CLAIMS RECORDED PLAT  7. Arthur O. Enger Add before the converge of the converge points mentioned in lines 1 and 2 above were, in a field survey on May 1 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United State Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:  A. Description of original monument and accessories and/or subsequent restoration:  Corner J3 (1/4 corner between Sections 2 & 11, T41N, R32W):  Y. Birch 22 for corner (Not found. No subsequent monuments found.)  No bearing trees (Not found. No subsequent monuments found.)  No bearing trees (Not found. No subsequent monuments found.)  No set in original survey nor subsequently, apparently.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Corner J3: Restored on line between Sec. Cor. 40,036 ch. to E and to W. An old N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.  Corner 1: Established on line between Sec. Cor. 20.018 ch. W and 1/4 cor. 20.018 ch. E.
2. PROPERTY CONTROLL-11 ,T. 41 N. R. 32 Y. 1  3. MISCELLANEOUS PROPERTY IN SECTION T. S., R. W. 4. LOT NO. RECORDED PLAT  5. PRIVATE CLAIMS REGISTER OF DEEDS STAMP AND FILING NUMBER  I. Arthur O. Enger
3. MISCELLANEOUS PROPERTY IN SECTION, T
Arthur O. Enger
Arthur O. Enger
I. Arthur O. Enger
the corner points mentioned in lines 1 and 2 above were, in a field survey on Nay 1, 19, 70, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:  A. Description of original monument and accessories and/or subsequent restoration:  Corner J3 (1/4 corner between Sections 2 & 11, T41N, R32W):  Y. Birch 22 for corner (Not found. No subsequent monuments found.)  No bearing trees (Not found. No subsequent accessories found.)  Corner 1 (West 1/16 corner between Sections 2 & 11, T41N, R32W):  Not set in original survey nor subsequently, apparently.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Corner J3: Restored on line between Sec. Cor. 40.036 ch. to E and to W. An old N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.
Corner J3 (1/4 corner between Sections 2 & 11, T41N, R32W):  Y. Birch 22 for corner (Not found. No subsequent monuments found.)  No bearing trees (Not found. No subsequent accessories found.)  Corner 1 (West 1/16 corner between Sections 2 & 11, T41N, R32W):  Not set in original survey nor subsequently, apparently.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Corner J3: Restored on line between Sec. Cor. 40.036 ch. to E and to W. An old N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.
Y. Birch 22 for corner (Not found. No subsequent monuments found.)  No bearing trees (Not found. No subsequent accessories found.)  Corner 1 (West 1/16 corner between Sections 2 & 11, T41N, R32W):  Not set in original survey nor subsequently, apparently.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Corner J3: Restored on line between Sec. Cor. 40.036 ch. to E and to W. An old N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.
Not set in original survey nor subsequently, apparently.  B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Corner J3: Restored on line between Sec. Cor. 40.036 ch. to E and to W. An old N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.
Corner J3: Restored on line between Sec. Cor. 40.036 ch. to E and to W. An old N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.
N & S fence line is 7 ft. E of corner, but there are no visible indications of an intersecting E & W fence line.
Corner 1: Established on line between Sec. Cor. 20.018 ch. W and 1/4 cor. 20.018 ch. E.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Corner J3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap Triple W. Birch 10 S62°W (mag.) 39.0 ft. "1/4S, NBT"  Red Maple 8 N72°E (mag.) 31.2 ft. "1/4S, NBT"  Declination is 0°30' East
Corner 1: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap  Red Oak 11 N16°E (mag.) 6.7 ft. "1/16S, BT"  Red Oak 12 S67°W (mag.) 19.8 ft. "1/16S, BT"  Declination 1°00' East.
SIGNED BY DATE
SURVEYOR'S MICHIGAN REGISTRATION NO
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY CHIEF OF SURVEY PARTY OF SURVEY PARTY
APPROVED AND SIGNED BY WITHIN O CHANGE DATE MICHIGAN REGISTERED LAND PROVED AND SIGNED BY MICHIGAN REGISTERED LAND PROVEYOR
Arthur O. Enger  Michigan Department of Natural Resources
SURVEYOR'S MICHIGAN REGISTRATION NO. 13581