LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42 N. ~~S.~~, R. 31 ~~E.~~ W.	J3 & K3
2. PROPERTY CONTROLLING IN SECTION 2	,T. 42 N. ~~S.~~, R. 31 ~~E.~~ W.	14
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19__, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner J3: Maple post (Not found. No subsequent monuments found.)
Hemlock 13 N50E 27 (" " " " accessories found.)
W. Pine 16 S41W 63 (" " " " " "

Corner K3: Sugar post (Not found. No subsequent monuments found.)
Y. Birch 12 S34E 27 (" " " " accessories found.)
Fir 8 N20W 18 (" " " " " "

Corner 14: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner J3: Re-established 5/22/74 on line between Sec. Cor. 39.879 ch. to E and to W.

Corner K3: Re-established 5/21/74 by double proportionate measurement between corners 1 mile E, 2 miles W, 2 miles S, and 1 mile N.

Corner 14: Established 5/31/74 on line between Sec. Cor. 20.050 ch. S and 1/4 cor. 20.050 ch. N. Corner falls in a 14" basswood tree; a monument was placed 2.0 feet E of true corner point.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for all three corners: 1" I.D. x 36" iron pipe with 3½" aluminum cap.

Witnesses for Corner J3: J. Pine 7 S87°E (mag.) 67.3 ft. "1/4S, NBT"
J. Pine 7 N72°E (mag.) 37.5 ft. "1/4S, NBT"

Witnesses for Corner K3: W. Spruce 8 S51°E (mag.) 55.6 ft. "S12, NBT"
W. Spruce 5 S26°W (mag.) 41.5 ft. "S11, NBT"

Witnesses for Corner 14: R. Pine 6 N10°E (mag.) 27.7 ft. "1/16S, BT"
R. Maple 6 S59°E (mag.) 12.8 ft. "1/16S, BT"

Note: Witnesses for this corner are to the iron pipe, not to the true corner .

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE November 26, 1974
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

STATE OF MICHIGAN ARTHUR O. ENGER LAND SURVEYOR No 13581 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

Form No. ML M736
GRAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS