

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 31 W


Iron COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Secs. 15/14

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/7/65 with Forester Rose

WITNESSES TO CORNER..... 16" Cedar (1/4S NBT), S 58° W, 33 Lks.



20" Cedar (1/4S NBT), N 06° W, 21 1/2 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from down Cedar with faces badly rotted (6" Cedar N 55° W, 15 Lks.) and stump bottom in proper distance and bearing and down post at Corner.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 2/10/1966
REGISTERED LAND SURVEYOR