

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
T Iron

	(County)	Located In	Corner Code #
1	Public Land Survey	T 42N R 31W	J8
		T R	
		T R	
		T R	
2	Property Controlling in Section	S 23 T R	9
		S T R	12
3	Miscellaneous Property in Sec	S T R	
		S T R	

Register of Deeds Stamp & File Number

4 Lot No _____, Recorded Plat _____
 5 Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	8	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Keith Sackett, in a field survey on April 24, 1990, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A Description of original monument and accessories and/or subsequent restoration:
 J8 9 12

Not set on original survey nor subsequently, apparently. Not set on original survey nor subsequently, apparently. Not set on original survey nor subsequently, apparently.

B Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J8 9 12
 Set at intersection of 1/4 lines. Established during section subdivision. Established during section subdivision.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner

J8 9 12
 Set 1" ID x 32" iron pipe w/4" aluminum cap. Set 1" ID x 32" iron pipe w/4" aluminum cap. Set 1" ID x 32" iron pipe w/4" aluminum cap in west side of Camp 5 Road ditch.
 7" sugar S81E 19.2' 1/4s, BT 7" sugar N85W 7.7' 1/16s, BT
 4" sugar N28E 13.6' 1/4s, BT 14" sugar S14W 10.9' 1/16s, BT 16" hemlock S70W 16.6' 1/16s, BT
 4" ironwood N52W 3.8' 1/4s, BT 6" sugar S69E 16.0' 1/16s, BT
 12" squared aspen south 2.0'



Signed by _____ Date August 27, 1990

Surveyor's Michigan License No _____

19006