## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

					Iron		COUNTY
				T	42N	R.	
DESCRIPTION OF CORNER _	Section	Corner	27, 28, 3	3, and 3	<u>4</u>	··-	
CORNER MONUMENT 1" I.D.	x 36" iro	n pipe w	ith 4" alu	minum c	ар		
DATE MONUMENT PLACED AND	WITNESSED	Ju	ne 15, 197	71			
WITNESSES TO CORNER	Aspen 1	0	(mag.) 9	5.6 ft.	"S34, NBT"		
N	Aspen	7 N26°E	(mag.) 49	).1 ft.	"\$27, NBT"		<del></del>
33							
	AND						
CIRCLE CORNER REGISTER	ED		· · ·				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a 13" I.D. x 6' iron pipe at approximate corner location, set by unknown party. As the found iron pipe falls only 6.4 ft. from the calculated proportionate corner position, it was accepted as reasonably representing the true original corner.

SURVEYOR'S SEAL

SIGNED

Arthur O. Enger

DATE September 28, 1972

DISTRIBUTION:

Forestry Division, Lansing

Area Forester

District Surveyor

R 4047 Rev. 1/72