STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Iren	COUNTY	
		T <u>42 N</u>	R 32 W	
DESCRIPTION OF CORNER	Section Corner 7, 8, 17, and	18		
CORNER MONUMENT1" I.I.	. x 36" galvanized iron pipe	with 4" alumin	num description	cap.
DATE MONUMENT PLACED AND I	WITNESSED May 19, 1970			
VITNESSES TO CORNER	Cedar 6 S39 W (magnetic)	6,2 feet "S18,	NBT"	
N	Cedar 6 N41°W (magnetic) 1	8.5 feet "S 7,	NBT*	
8	Cedar 6 N30°W (magnetic) 1	0.1 feet "S 8,	NBT"	
	AND			
CIRCLE CORNER REGISTERE	D			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a 3"x3"x3½ squared cedar post in place and point of an older cedar post in the swamp peat, possibly part of the original monument. From the posts, measured out the recorded bearings and distances to the original BT's, and found remains of both trees lying under the swamp moss, with description and witness faces plain, but scribe marks obliterated.

SURVEYOR'S SEAL

STONE

REGISTERED LAND SURVEYOR

DATE

April 26, 197

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047
Rev. 10/68