STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Iron	COUNTY
		T 42 N	R32 W
DESCRIPTION OF CORNER	L/4 corner between Sections 31	L and 32	
CORNER MONUMENT 1" I.D. x 36" galvanized iron pipe with 4" aluminum description cap.			
DATE MONUMENT PLACED AND WITNESSED May 7, 1970			
ITNESSES TO CORNER	W. Pine 7 N65°W (magnet	tic) 53.4 feet	"1/4S, NBT"
N32	Red Maple 6 N73°E (magnet	tic) 11.5 feet	"1/4S, NBT"
	AND		
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a rusty 1" I.D. x 36" iron pipe about 25 feet SW*ly of previously calculated corner position. Found fragments of a white pine stump bearing S75°E 21 links from this pipe, corresponding to one of the original BT*s. As it seemed probable that the pipe and pine fragments marked the original corner location, I accepted them as doing so.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE

April 29, 197

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing