STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Iron	COUNTY
		τ <u>41-42N</u>	R32W
DESCRIPTION OF CORNER	Section Corner 5, 6, 31	, and 32	
CORNER MONUMENT	D. x 36" iron pipe with 4"	aluminum cap	·
DATE MONUMENT PLACED AND	WITNESSED April 23,	1970	
ITNESSES TO CORNER	. Balsam ⁷ S38°E (mag.) 23.6 ft. "S	5, NBT"
N	W. Pine 6 N64½°E (mag.) 37.2 ft. "S32	2, NBT"
32	B. Spruce 5 N46½°W (mag.) 12.1 ft. "S3	l, NBT"
	AND		
CIRCLE CORNER REGISTER	ED	······································	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a Land Economic Survey wood post placed in early 1930's for an approximate corner. Reluctantly accepted the L.E.S.post as the corner, as local use of the position would probably create confusion and possible hardship if changed. L.E.S. post is plainly marked "approximate", but such posts were placed by measurement from known corners by staff compass and steel tape, with a search being made for original evidence. There is no record of any being found when the L.E.S. post was set. It is believed by the undersigned that the original corner was perhaps 40 links or so southerly of the L.E.S. post.

SURVEYOR'S SEAL

SIGNED

___ D/

May 31, 197

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing