LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

Corner Code #

Located In:

For corners in Iron

(County)

	12N R 34W 18	
T	12N R 34W G7	
' S T	R R	
2. Property Controlling ST_	R	
in Section S T	R	
3. Miscellaneous S T	R	Register of Deeds Stamp & File Number
Property in Sec. S T	R	
4. Lot No, Recorded Plat		A B C D E F G H I J K L M
5. Private Claims	G7 Apr 21 2004	2 - 5 - 5 - 4 - 3 - 4 - 2 - 4 - 1 - 1
	IB Apr 20 2004	3
I, Stephan J. Szyszkoski , in a field	·	4 - 7 8 9 10 11 12 - 12
	survey on, 20 do hereby says of 1970, the corner points mentioned in lines 1 a	
above were in conformance with regulations and rules therefore as required in the current manual of 6 18 17 16 15 14 13		
survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in		
	rd of Land Surveyors or by a Decree of a Court of	
established, re-established, monumented, recover	red, found as expressed below:	9
NOTE: Not more than 2 corners, all in t	he same town and range, may be recorded	
on this certificate.		11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of original monument and a	ccessories and/or subsequent restoration:	12 31 32 33 34 35 36
(I8) Quarter corner common to Sections 22-23. Established in 1851 by Guy Carleton: "[south] on true line between Sections 22 and 23 40.00 Set quarter post. Cedar 10 N72E 20 links, Sugar 8 S60W 26 links44.76 Intersect left bank of Brule river and set Meander post." Old Chicago and Northwestern RR plans (probably ca. 1920) show distances north 255' to C/L spur to Chicagon Mine, west 140' to same, south 231' to C/L of main line. (G7) Corner common to Sections 15-16-21-22. Established in 1851 by Guy Carleton. Set post corner of Sections 15,16,21, and 22 in edge of swamp. Aspen 16 S17W 34 links, Yellow Birch 10 N62E 10 links. Notes acquired from Gary Pisoni, PS, in 1984 show 3/4" iron pipe marking the corner and a distance to E7 of 5246.20'.		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
(I8) The original post and accessories were not recovered. Recovered the C/L of the abandoned RR grades noted above and reestablished the corner at record distance from all, at record GLO distance, indexed, from the reestablished Meander corner on the bank of the Brule River, 313.84' south, and 2637.51' south of I7 (2640 GLO). (G7) The original post and accessories were not recovered. Found and accepted a 3/4" iron pipe, projecting 8" above ground with a drill rod, projecting 36", driven adjacent. Distance west to E7 of 5246.77' checks well with the notes of Mr. Pisoni.		
C. Description of monument for corner and	d accessories established to perpetuate locat	ting the position of the corner:
(I8) Set 1"IDx32" I.pipe with 4" alum.	(G7) Found 3/4" iron pipe, projecting 8 above ground. Blazed, scribed, and set	
MDNR cap. Blazed, scribed, and set measuring nails in:	measuring nails in:	
5" W.Spruce N40E 34.5' "1/4S NBT"	6" Spruce N44E 33.9' "S15 NBT"	* STEPHAN J.
6" W.Spruce S30E 35.9' do	7" Spruce N80E 31.8' do	* SZYSZKOSKI
15" Hemlack S46W 37.0' do 5" W.Spruce N12W 11.3' do	12" Tamarack S67W 15.4' "S21 NBT" 7" Tamarack N62W 39.9' "S16 NBT"	LAND **
5" M.Spruce N12W 11.3' do Set sq'd cedar post adjacent. Bearings	6'tall cedar post adjacent. Bearings	No.
are magnetic. Distances are to nail	are magnetic. Distances are to nail	33986
with tag.	with tag.	AND S
1. 1. 1. 1		
Signed by Steph	iphol'	Date 6/17/04
Surveyor's Michigan License No.	33986	
For the Micl	nigan Department of Natural Resources, Offic	ce of Land and Facilities
	FORM APPRO	IVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19 Revised May 14, 11
		Revised Jan., 15 Rervised Oct., 15