Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

AND

CIRCLE CORNER REGISTERED

This corner was replaced from old down squared wood post, set by unknown surveyor.

Distance east to stream fits = 15.00 chains.

SURVEYOR'S SEAL

SIGNED Silly V. Suckles DATE 3/17/61

REGISTERED LAND SURVEYOR

Billy D. Buckler